

ID GPS	Tipo	Corr.	Código de Barras	Latitud	Longitud	Fecha/Hora/GMT GPS	String ORG.	Fecha/Sistema	LINK
0002	S	0000		0	0		>S0002<	12/6/2007 10:25:26 AM	86512
0002	P	0000	B200498075318	0	0	12/6/2007 10:25:26 AM	>P00020000;B200498075318;F/W v1.3egps, Nov 15 2007.<	12/6/2007 10:25:26 AM	86513
0002	E	0000		0	0		>E0002;0003<	12/6/2007 10:25:26 AM	86514
0002	S	0000		0	0		>S0002<	12/6/2007 10:37:30 AM	86535
0002	T	0001		-33.488568333333	-70.6113966666667	12/6/2007 10:31:05 AM	>T00020001;033293141;070366838;071206;133105<	12/6/2007 10:37:30 AM	86536
0002	T	0002		-33.488568333333	-70.6113966666667	12/6/2007 10:34:08 AM	>T00020002;033293141;070366838;071206;133408<	12/6/2007 10:37:30 AM	86537
0002	T	0003		-33.488568333333	-70.6113966666667	12/6/2007 10:37:11 AM	>T00020003;033293141;070366838;071206;133711<	12/6/2007 10:37:30 AM	86538
0002	E	0000		0	0		>E0002;0005<	12/6/2007 10:37:30 AM	86539
0002	S	0000		0	0		>S0002<	12/6/2007 10:47:55 AM	86572
0002	T	0004		-33.488568333333	-70.6113966666667	12/6/2007 10:40:36 AM	>T00020004;033293141;070366838;071206;134036<	12/6/2007 10:47:55 AM	86573
0002	T	0005		-33.488568333333	-70.6113966666667	12/6/2007 10:43:39 AM	>T00020005;033293141;070366838;071206;134339<	12/6/2007 10:47:55 AM	86574
0002	T	0006		-33.488398333333	-70.6112616666667	12/6/2007 10:46:45 AM	>T00020006;033293039;070366757;071206;134645<	12/6/2007 10:47:55 AM	86575
0002	E	0000		0	0		>E0002;0005<	12/6/2007 10:47:55 AM	86576
0002	S	0000		0	0		>S0002<	12/6/2007 10:57:56 AM	86596
0002	T	0007		-33.4883716666667	-70.6111816666667	12/6/2007 10:48:45 AM	>T00020007;033293023;070366709;071206;134845<	12/6/2007 10:57:56 AM	86597
0002	T	0008		-	-70.61118	12/6/2007 10:52:39 AM	>T00020008;033293017;0703667	12/6/2007	8659

				33.48836166666 67			08;071206;135239<	10:57:56 AM	8
0002	T	0009		- 33.48743333333 33	- 70.61105333333 33	12/6/2007 10:55:35 AM	>T00020009;033292460;0703666 32;071206;135535<	12/6/2007 10:57:56 AM	8659 9
0002	E	0000		0	0		>E0002;0005<	12/6/2007 10:57:56 AM	8660 0
0002	S	0000		0	0		>S0002<	12/6/2007 11:07:57 AM	8663 1
0002	T	0010		- 33.48784166666 67	-70.6112	12/6/2007 10:58:45 AM	>T00020010;033292705;0703667 20;071206;135845<	12/6/2007 11:07:57 AM	8663 2
0002	T	0011		-33.483265	- 70.61290166666 67	12/6/2007 11:02:45 AM	>T00020011;033289959;0703677 41;071206;140245<	12/6/2007 11:07:57 AM	8663 3
0002	T	0012		- 33.47564166666 67	- 70.61337666666 67	12/6/2007 11:05:30 AM	>T00020012;033285385;0703680 26;071206;140530<	12/6/2007 11:07:57 AM	8663 4
0002	E	0000		0	0		>E0002;0005<	12/6/2007 11:07:57 AM	8663 5
0002	S	0000		0	0		>S0002<	12/6/2007 11:18:05 AM	8668 2
0002	T	0013		- 33.46806833333 33	-70.6139	12/6/2007 11:08:45 AM	>T00020013;033280841;0703683 40;071206;140845<	12/6/2007 11:18:05 AM	8668 3
0002	T	0014		-33.4613	-70.61855	12/6/2007 11:12:45 AM	>T00020014;033276780;0703711 30;071206;141245<	12/6/2007 11:18:05 AM	8668 4
0002	T	0015		- 33.45639666666 67	- 70.62541333333 33	12/6/2007 11:15:45 AM	>T00020015;033273838;0703752 48;071206;141545<	12/6/2007 11:18:05 AM	8668 5
0002	E	0000		0	0		>E0002;0005<	12/6/2007 11:18:05 AM	8668 6
0002	S	0000		0	0		>S0002<	12/6/2007 11:28:08 AM	8670 7
0002	T	0016		- 33.45270166666 67	- 70.63067333333 33	12/6/2007 11:18:45 AM	>T00020016;033271621;0703784 04;071206;141845<	12/6/2007 11:28:08 AM	8670 8
0002	T	0017		- 33.45028833333 33	- 70.63863333333 33	12/6/2007 11:22:45 AM	>T00020017;033270173;0703831 80;071206;142245<	12/6/2007 11:28:08 AM	8670 9
0002	T	0018		-	-	12/6/2007 11:25:45 AM	>T00020018;033271081;0703870	12/6/2007	8671

				33.451801666667	70.645038333333		23;071206;142545<	11:28:08 AM	0
0002	E	0000		0	0		>E0002;0005<	12/6/2007 11:28:08 AM	86711
0002	S	0000		0	0		>S0002<	12/6/2007 11:38:09 AM	86793
0002	T	0019		-33.45215	- 70.651446666667	12/6/2007 11:28:50 AM	>T00020019;033271290;070390868;071206;142850<	12/6/2007 11:38:09 AM	86794
0002	T	0020		- 33.449473333333	- 70.659163333333	12/6/2007 11:32:45 AM	>T00020020;033269684;070395498;071206;143245<	12/6/2007 11:38:09 AM	86795
0002	T	0021		- 33.443383333333	-70.660065	12/6/2007 11:35:45 AM	>T00020021;033266030;070396039;071206;143545<	12/6/2007 11:38:09 AM	86796
0002	E	0000		0	0		>E0002;0005<	12/6/2007 11:38:09 AM	86797
0002	S	0000		0	0		>S0002<	12/6/2007 11:48:05 AM	86850
0002	T	0022		- 33.443128333333	- 70.660031666667	12/6/2007 11:38:45 AM	>T00020022;033265877;070396019;071206;143845<	12/6/2007 11:48:05 AM	86851
0002	T	0023		-33.437815	- 70.664488333333	12/6/2007 11:42:48 AM	>T00020023;033262689;070398693;071206;144248<	12/6/2007 11:48:05 AM	86852
0002	T	0024		- 33.436948333333	- 70.673493333333	12/6/2007 11:45:45 AM	>T00020024;033262169;070404096;071206;144545<	12/6/2007 11:48:05 AM	86853
0002	E	0000		0	0		>E0002;0005<	12/6/2007 11:48:05 AM	86854
0002	S	0000		0	0		>S0002<	12/6/2007 11:58:03 AM	86947
0002	T	0025		-33.438005	-70.68073	12/6/2007 11:48:42 AM	>T00020025;033262803;070408438;071206;144842<	12/6/2007 11:58:03 AM	86948
0002	T	0026		- 33.440478333333	- 70.680943333333	12/6/2007 11:52:45 AM	>T00020026;033264287;070408566;071206;145245<	12/6/2007 11:58:03 AM	86949
0002	T	0027		- 33.440466666667	-70.680935	12/6/2007 11:55:45 AM	>T00020027;033264280;070408561;071206;145545<	12/6/2007 11:58:03 AM	86950
0002	E	0000		0	0		>E0002;0005<	12/6/2007	8695

								11:58:03 AM	1
0002	S	0000		0	0		>S0002<	12/6/2007 12:08:05 PM	87066
0002	T	0028		-33.440458333333	-70.68093	12/6/2007 11:58:45 AM	>T00020028;033264275;070408558;071206;145845<	12/6/2007 12:08:05 PM	87067
0002	T	0029		-33.440491666667	-70.68102	12/6/2007 12:02:45 PM	>T00020029;033264295;070408612;071206;150245<	12/6/2007 12:08:05 PM	87068
0002	T	0030		-33.440505	-70.681098333333	12/6/2007 12:05:45 PM	>T00020030;033264303;070408659;071206;150545<	12/6/2007 12:08:05 PM	87069
0002	E	0000		0	0		>E0002;0005<	12/6/2007 12:08:05 PM	87070
0002	S	0000		0	0		>S0002<	12/6/2007 12:18:07 PM	87144
0002	T	0031		-33.440481666667	-70.681088333333	12/6/2007 12:08:45 PM	>T00020031;033264289;070408653;071206;150845<	12/6/2007 12:18:07 PM	87145
0002	T	0032		-33.440486666667	-70.680943333333	12/6/2007 12:12:45 PM	>T00020032;033264292;070408566;071206;151245<	12/6/2007 12:18:07 PM	87146
0002	T	0033		-33.440428333333	-70.680555	12/6/2007 12:15:45 PM	>T00020033;033264257;070408333;071206;151545<	12/6/2007 12:18:07 PM	87147
0002	E	0000		0	0		>E0002;0005<	12/6/2007 12:18:07 PM	87148
0002	S	0000		0	0		>S0002<	12/6/2007 12:29:55 PM	87309
0002	T	0034		-33.43956	-70.679856666667	12/6/2007 12:18:45 PM	>T00020034;033263736;070407914;071206;151845<	12/6/2007 12:29:55 PM	87310
0002	T	0035		-33.438368333333	-70.679926666667	12/6/2007 12:22:45 PM	>T00020035;033263021;070407956;071206;152245<	12/6/2007 12:29:55 PM	87311
0002	D	0036	692007418426	-33.437101666667	-70.68018	12/6/2007 12:24:45 PM	>D00020036;692007418426;033262261;070408108;071206;152445<	12/6/2007 12:29:55 PM	87312
0002	T	0037		-33.435135	-70.680325	12/6/2007 12:26:45 PM	>T00020037;033261081;070408195;071206;152645<	12/6/2007 12:29:55 PM	87313
0002	D	0038	692007459014	-33.43432	-70.680435	12/6/2007 12:27:54 PM	>D00020038;692007459014;0332	12/6/2007	8731

							60592;070408261;071206;152754 <	12:29:55 PM	4
0002	D	0039	692007477066	-33.43432	-70.680435	12/6/2007 12:27:54 PM	>D00020039;692007477066;0332 60592;070408261;071206;152754 <	12/6/2007 12:29:55 PM	8731 5
0002	D	0040	692007418214	-33.43432	-70.680435	12/6/2007 12:27:54 PM	>D00020040;692007418214;0332 60592;070408261;071206;152754 <	12/6/2007 12:29:55 PM	8731 6
0002	D	0041	80762342328	-33.4339	-70.680455	12/6/2007 12:29:30 PM	>D00020041;80762342328;03326 0340;070408273;071206;152930<	12/6/2007 12:29:55 PM	8731 7
0002	T	0042		-33.434085	-70.680635	12/6/2007 12:30:45 PM	>T00020042;033260451;0704083 81;071206;153045<	12/6/2007 12:29:55 PM	8731 8
0002	E	0000		0	0		>E0002;0011<	12/6/2007 12:29:55 PM	8731 9
0002	S	0000		0	0		>S0002<	12/6/2007 12:44:56 PM	8740 6
0002	D	0043	@@200491677617	- 33.43292333333	-70.68041	12/6/2007 12:33:15 PM	>D00020043;@@200491677617;0 33259754;070408246;071206;153 315<	12/6/2007 12:44:56 PM	8740 7
0002	T	0044		- 33.43356166666 67	- 70.68027666666 67	12/6/2007 12:34:24 PM	>T00020044;033260137;0704081 66;071206;153424<	12/6/2007 12:44:56 PM	8740 8
0002	D	0045	80763692284	-33.433325	-70.68026	12/6/2007 12:36:19 PM	>D00020045;80763692284;03325 9995;070408156;071206;153619<	12/6/2007 12:44:56 PM	8740 9
0002	D	0046	51200711300232045	- 33.43190833333	- 70.68028166666 67	12/6/2007 12:38:15 PM	>D00020046;51200711300232045 ;033259145;070408169;071206;1 53815<	12/6/2007 12:44:56 PM	8741 0
0002	T	0047		- 33.43084333333	-70.680535	12/6/2007 12:39:09 PM	>T00020047;033258506;0704083 21;071206;153909<	12/6/2007 12:44:56 PM	8741 1
0002	D	0048	692007448617	- 33.43067333333	- 70.68057333333 33	12/6/2007 12:39:30 PM	>D00020048;692007448617;0332 58404;070408344;071206;153930 <	12/6/2007 12:44:56 PM	8741 2
0002	D	0049	8076255855@@	- 33.43067333333	- 70.68057333333 33	12/6/2007 12:39:30 PM	>D00020049;8076255855@@;033 258404;070408344;071206;15393 0<	12/6/2007 12:44:56 PM	8741 3
0002	D	0050	692007416919	- 33.43067333333	- 70.68057333333 33	12/6/2007 12:39:30 PM	>D00020050;692007416919;0332 58404;070408344;071206;153930 <	12/6/2007 12:44:56 PM	8741 4
0002	D	0051	8076426698@@	- 33.42968666666 67	-70.680685	12/6/2007 12:40:45 PM	>D00020051;8076426698@@;033 257812;070408411;071206;15404 5<	12/6/2007 12:44:56 PM	8741 5
0002	D	0052	51200711300230662	-33.42903	-	12/6/2007 12:42:38 PM	>D00020052;51200711300230662	12/6/2007	8741

					70.68048166666 67		;033257418;070408289;071206;1 54238<	12:44:56 PM	6
0002	D	0053	@@200038079917	-33.42884	- 70.68014833333 33	12/6/2007 12:43:35 PM	>D00020053;@@200038079917;0 33257304;070408089;071206;154 335<	12/6/2007 12:44:56 PM	8741 7
0002	T	0054		- 33.42885666666 67	- 70.68001833333 33	12/6/2007 12:44:30 PM	>T00020054;033257314;0704080 11;071206;154430<	12/6/2007 12:44:56 PM	8741 8
0002	D	0055	80762787915	- 33.42879166666 67	- 70.67893666666 67	12/6/2007 12:45:45 PM	>D00020055;80762787915;03325 7275;070407362;071206;154545<	12/6/2007 12:44:56 PM	8741 9
0002	E	0000		0	0		>E0002;0015<	12/6/2007 12:44:56 PM	8742 0
0002	S	0000		0	0		>S0002<	12/6/2007 1:00:27 PM	8757 0
0002	D	0056	51200711300237020	- 33.42925166666 67	- 70.67707666666 67	12/6/2007 12:47:45 PM	>D00020056;51200711300237020 ;033257551;070406246;071206;1 54745<	12/6/2007 1:00:27 PM	8757 1
0002	T	0057		- 33.42935166666 67	- 70.67723833333 33	12/6/2007 12:48:41 PM	>T00020057;033257611;0704063 43;071206;154841<	12/6/2007 1:00:27 PM	8757 2
0002	D	0058	692007418916	-33.42935	- 70.67645833333 33	12/6/2007 12:50:06 PM	>D00020058;692007418916;0332 57610;070405875;071206;155006 <	12/6/2007 1:00:27 PM	8757 3
0002	D	0059	51200711280075975	-33.429355	-70.67597	12/6/2007 12:51:15 PM	>D00020059;51200711280075975 ;033257613;070405582;071206;1 55115<	12/6/2007 1:00:27 PM	8757 4
0002	D	0060	800447330720	- 33.42970833333 33	- 70.67596833333 33	12/6/2007 12:52:30 PM	>D00020060;800447330720;0332 57825;070405581;071206;155230 <	12/6/2007 1:00:27 PM	8757 5
0002	D	0061	51200711300235974	- 33.42970833333 33	- 70.67596833333 33	12/6/2007 12:52:30 PM	>D00020061;51200711300235974 ;033257825;070405581;071206;1 55230<	12/6/2007 1:00:27 PM	8757 6
0002	D	0062	80763599632	- 33.42980666666 67	-70.67594	12/6/2007 12:53:15 PM	>D00020062;80763599632;03325 7884;070405564;071206;155315<	12/6/2007 1:00:27 PM	8757 7
0002	D	0063	80760077538	- 33.42980666666 67	-70.67594	12/6/2007 12:53:15 PM	>D00020063;80760077538;03325 7884;070405564;071206;155315<	12/6/2007 1:00:27 PM	8757 8
0002	T	0064		- 33.42973333333 33	- 70.67589666666 67	12/6/2007 12:54:15 PM	>T00020064;033257840;0704055 38;071206;155415<	12/6/2007 1:00:27 PM	8757 9
0002	D	0065	692007413759	- 33.42948166666 67	-70.67572	12/6/2007 12:55:00 PM	>D00020065;692007413759;0332 57689;070405432;071206;155500 <	12/6/2007 1:00:27 PM	8758 0
0002	D	0066	@@200488789415	-	-70.67572	12/6/2007 12:55:00 PM	>D00020066;@@200488789415;0	12/6/2007	8758

				33.429481666667			33257689;070405432;071206;15500<	1:00:27 PM	1
0002	D	0067	692007479876	-33.429015	-70.67461	12/6/2007 12:57:30 PM	>D00020067;692007479876;033257409;070404766;071206;155730<	12/6/2007 1:00:27 PM	87582
0002	T	0068		-33.429008333333	-70.674548333333	12/6/2007 12:58:30 PM	>T00020068;033257405;070404729;071206;155830<	12/6/2007 1:00:27 PM	87583
0002	D	0069	800446673765	-33.42902	-70.674426666667	12/6/2007 12:59:00 PM	>D00020069;800446673765;033257412;070404656;071206;155900<	12/6/2007 1:00:27 PM	87584
0002	E	0000		0	0		>E0002;0016<	12/6/2007 1:00:27 PM	87585
0002	S	0000		0	0		>S0002<	12/6/2007 1:12:24 PM	87631
0002	D	0070	800446707201	-33.428138333333	-70.676188333333	12/6/2007 1:01:15 PM	>D00020070;800446707201;033256883;070405713;071206;160115<	12/6/2007 1:12:24 PM	87632
0002	T	0071		-33.428138333333	-70.676188333333	12/6/2007 1:01:15 PM	>T00020071;033256883;070405713;071206;160115<	12/6/2007 1:12:24 PM	87633
0002	D	0072	800446704804	-33.426873333333	-70.677393333333	12/6/2007 1:04:18 PM	>D00020072;800446704804;033256124;070406436;071206;160418<	12/6/2007 1:12:24 PM	87634
0002	T	0073		-33.42687	-70.677316666667	12/6/2007 1:06:15 PM	>T00020073;033256122;070406390;071206;160615<	12/6/2007 1:12:24 PM	87635
0002	D	0074	800447255874	-33.428746666667	-70.677911666667	12/6/2007 1:08:50 PM	>D00020074;800447255874;033257248;070406747;071206;160850<	12/6/2007 1:12:24 PM	87636
0002	T	0075		-33.429083333333	-70.678156666667	12/6/2007 1:10:06 PM	>T00020075;033257450;070406894;071206;161006<	12/6/2007 1:12:24 PM	87637
0002	E	0000		0	0		>E0002;0008<	12/6/2007 1:12:24 PM	87638
0002	S	0000		0	0		>S0002<	12/6/2007 1:28:35 PM	87672
0002	T	0076		-33.429191666667	-70.679646666667	12/6/2007 1:12:45 PM	>T00020076;033257515;070407788;071206;161245<	12/6/2007 1:28:35 PM	87673
0002	D	0077	@@200498754918	-33.42946	-70.67982	12/6/2007 1:16:30 PM	>D00020077;@@200498754918;033257676;070407892;071206;161630<	12/6/2007 1:28:35 PM	87674
0002	D	0078	8076268282@@	-	-	12/6/2007 1:17:00 PM	>D00020078;8076268282@@;033	12/6/2007	8767

				33.429468333333	70.679816666667		257681;070407890;071206;161700<	1:28:35 PM	5
0002	D	0079	800446665092	-33.429585	- 70.679843333333	12/6/2007 1:18:00 PM	>D00020079;800446665092;033257751;070407906;071206;161800<	12/6/2007 1:28:35 PM	87676
0002	T	0080		- 33.429578333333	- 70.679723333333	12/6/2007 1:19:00 PM	>T00020080;033257747;070407834;071206;161900<	12/6/2007 1:28:35 PM	87677
0002	D	0081	80761942569	-33.429585	- 70.679626666667	12/6/2007 1:19:15 PM	>D00020081;80761942569;033257751;070407776;071206;161915<	12/6/2007 1:28:35 PM	87678
0002	D	0082	692007440028	- 33.429726666667	-70.67987	12/6/2007 1:21:00 PM	>D00020082;692007440028;033257836;070407922;071206;162100<	12/6/2007 1:28:35 PM	87679
0002	D	0083	80764338220	- 33.429726666667	-70.67987	12/6/2007 1:21:00 PM	>D00020083;80764338220;033257836;070407922;071206;162100<	12/6/2007 1:28:35 PM	87680
0002	D	0084	@@200038169217	- 33.429868333333	- 70.679641666667	12/6/2007 1:22:45 PM	>D00020084;@@200038169217;033257921;070407785;071206;162245<	12/6/2007 1:28:35 PM	87681
0002	D	0085	67202287	- 33.430023333333	- 70.679778333333	12/6/2007 1:23:30 PM	>D00020085;67202287;033258014;070407867;071206;162330<	12/6/2007 1:28:35 PM	87682
0002	T	0086		- 33.430043333333	-70.67965	12/6/2007 1:24:39 PM	>T00020086;033258026;070407790;071206;162439<	12/6/2007 1:28:35 PM	87683
0002	D	0087	80762110796	-33.430135	- 70.678956666667	12/6/2007 1:25:15 PM	>D00020087;80762110796;033258081;070407374;071206;162515<	12/6/2007 1:28:35 PM	87684
0002	D	0088	51200711280075541	-33.430325	- 70.679056666667	12/6/2007 1:26:45 PM	>D00020088;51200711280075541;033258195;070407434;071206;162645<	12/6/2007 1:28:35 PM	87685
0002	D	0089	67147901	-33.43018	- 70.679953333333	12/6/2007 1:28:15 PM	>D00020089;67147901;033258108;070407972;071206;162815<	12/6/2007 1:28:35 PM	87686
0002	E	0000		0	0		>E0002;0016<	12/6/2007 1:28:35 PM	87687
0002	S	0000		0	0		>S0002<	12/6/2007 1:42:33 PM	87785
0002	D	0090	51200712010200731	- 33.430336666667	- 70.680016666667	12/6/2007 1:29:15 PM	>D00020090;51200712010200731;033258202;070408010;071206;162915<	12/6/2007 1:42:33 PM	87786
0002	T	0091		- 33.430336666667	- 70.680016666667	12/6/2007 1:29:15 PM	>T00020091;033258202;070408010;071206;162915<	12/6/2007 1:42:33 PM	87787
0002	T	0092		-33.431065	-70.679565	12/6/2007 1:32:45 PM	>T00020092;033258639;0704077	12/6/2007	8778

							39;071206;163245<	1:42:33 PM	8
0002	T	0093		-33.4314	- 70.67781666666 67	12/6/2007 1:35:45 PM	>T00020093;033258840;0704066 90;071206;163545<	12/6/2007 1:42:33 PM	8778 9
0002	D	0094	80760337858	-33.431405	- 70.67800166666 67	12/6/2007 1:36:15 PM	>D00020094;80760337858;03325 8843;070406801;071206;163615<	12/6/2007 1:42:33 PM	8779 0
0002	D	0095	80759219868	- 33.43144666666 67	-70.678005	12/6/2007 1:36:45 PM	>D00020095;80759219868;03325 8868;070406803;071206;163645<	12/6/2007 1:42:33 PM	8779 1
0002	D	0096	80759701821	- 33.43157666666 67	- 70.67806666666 67	12/6/2007 1:37:30 PM	>D00020096;80759701821;03325 8946;070406840;071206;163730<	12/6/2007 1:42:33 PM	8779 2
0002	D	0097	7170711280200300	-33.431725	- 70.67995666666 67	12/6/2007 1:39:15 PM	>D00020097;7170711280200300; 033259035;070407974;071206;16 3915<	12/6/2007 1:42:33 PM	8779 3
0002	T	0098		- 33.43176833333 33	- 70.67942666666 67	12/6/2007 1:41:15 PM	>T00020098;033259061;0704076 56;071206;164115<	12/6/2007 1:42:33 PM	8779 4
0002	D	0099	51200711280076459	- 33.43238333333 33	- 70.67938833333 33	12/6/2007 1:42:15 PM	>D00020099;51200711280076459 ;033259430;070407633;071206;1 64215<	12/6/2007 1:42:33 PM	8779 5
0002	D	0100	@@200492884917	- 33.43282833333 33	- 70.67940166666 67	12/6/2007 1:43:15 PM	>D00020100;@@200492884917;0 33259697;070407641;071206;164 315<	12/6/2007 1:42:33 PM	8779 6
0002	E	0000		0	0		>E0002;0013<	12/6/2007 1:42:33 PM	8779 7
0002	S	0000		0	0		>S0002<	12/6/2007 2:00:23 PM	8805 7
0002	D	0101	51200712010192054	- 33.43282833333 33	- 70.67940166666 67	12/6/2007 1:43:15 PM	>D00020101;51200712010192054 ;033259697;070407641;071206;1 64315<	12/6/2007 2:00:23 PM	8805 8
0002	D	0102	@@200490420717	- 33.43335166666 67	-70.67914	12/6/2007 1:45:00 PM	>D00020102;@@200490420717;0 33260011;070407484;071206;164 500<	12/6/2007 2:00:23 PM	8805 9
0002	D	0103	51200712010192267	- 33.43395333333 33	- 70.67928166666 67	12/6/2007 1:46:45 PM	>D00020103;51200712010192267 ;033260372;070407569;071206;1 64645<	12/6/2007 2:00:23 PM	8806 0
0002	D	0104	51200711300233432	-33.43404	- 70.67928833333 33	12/6/2007 1:47:30 PM	>D00020104;51200711300233432 ;033260424;070407573;071206;1 64730<	12/6/2007 2:00:23 PM	8806 1
0002	T	0105		- 33.43438666666 67	- 70.67925666666 67	12/6/2007 1:48:30 PM	>T00020105;033260632;0704075 54;071206;164830<	12/6/2007 2:00:23 PM	8806 2
0002	D	0106	692007480912	-	-70.67933	12/6/2007 1:49:00 PM	>D00020106;692007480912;0332	12/6/2007	8806

				33.434768333333			60861;070407598;071206;164900<	2:00:23 PM	3
0002	D	0107	51200712010195258	- 33.435978333333	- 70.679041666667	12/6/2007 1:51:00 PM	>D00020107;51200712010195258;033261587;070407425;071206;165100<	12/6/2007 2:00:23 PM	88064
0002	D	0108	51200711280074219	- 33.435978333333	- 70.679041666667	12/6/2007 1:51:00 PM	>D00020108;51200711280074219;033261587;070407425;071206;165100<	12/6/2007 2:00:23 PM	88065
0002	D	0109	800447334079	- 33.436088333333	- 70.679133333333	12/6/2007 1:51:45 PM	>D00020109;800447334079;033261653;070407480;071206;165145<	12/6/2007 2:00:23 PM	88066
0002	D	0110	800447334084	- 33.436683333333	- 70.679133333333	12/6/2007 1:52:53 PM	>D00020110;800447334084;033262010;070407480;071206;165253<	12/6/2007 2:00:23 PM	88067
0002	D	0111	8076412624@@	-33.437015	- 70.679016666667	12/6/2007 1:54:00 PM	>D00020111;8076412624@@;033262209;070407410;071206;165400<	12/6/2007 2:00:23 PM	88068
0002	D	0112	80761988682	-33.437015	- 70.679016666667	12/6/2007 1:54:00 PM	>D00020112;80761988682;033262209;070407410;071206;165400<	12/6/2007 2:00:23 PM	88069
0002	T	0113		-33.437295	- 70.679493333333	12/6/2007 1:56:00 PM	>T00020113;033262377;070407696;071206;165600<	12/6/2007 2:00:23 PM	88070
0002	T	0114		- 33.437441666667	- 70.679168333333	12/6/2007 1:59:00 PM	>T00020114;033262465;070407501;071206;165900<	12/6/2007 2:00:23 PM	88071
0002	E	0000		0	0		>E0002;0016<	12/6/2007 2:00:23 PM	88072
0002	S	0000		0	0		>S0002<	12/6/2007 2:11:43 PM	88125
0002	T	0115		-33.4383	-70.678715	12/6/2007 2:01:00 PM	>T00020115;033262980;070407229;071206;170100<	12/6/2007 2:11:43 PM	88126
0002	D	0116	@@200499793118	-33.4383	-70.678715	12/6/2007 2:01:00 PM	>D00020116;@@200499793118;033262980;070407229;071206;170100<	12/6/2007 2:11:43 PM	88127
0002	D	0117	692007458564	- 33.436893333333	- 70.677931666667	12/6/2007 2:03:45 PM	>D00020117;692007458564;033262136;070406759;071206;170345<	12/6/2007 2:11:43 PM	88128
0002	D	0118	692007416664	- 33.436733333333	- 70.677941666667	12/6/2007 2:05:15 PM	>D00020118;692007416664;033262040;070406765;071206;170515<	12/6/2007 2:11:43 PM	88129
0002	D	0119	@@200497713218	- 33.436733333333	- 70.677941666667	12/6/2007 2:05:15 PM	>D00020119;@@200497713218;033262040;070406765;071206;170515<	12/6/2007 2:11:43 PM	88130
0002	T	0120		-	-	12/6/2007 2:06:16 PM	>T00020120;033261832;0704068	12/6/2007	8813

				33.436386666667	70.678141666667		85;071206;170616<	2:11:43 PM	1
0002	D	0121	80760299530	- 33.436101666667	- 70.678421666667	12/6/2007 2:07:30 PM	>D00020121;80760299530;033261661;070407053;071206;170730<	12/6/2007 2:11:43 PM	88132
0002	T	0122		- 33.435328333333	- 70.678146666667	12/6/2007 2:09:27 PM	>T00020122;033261197;070406888;071206;170927<	12/6/2007 2:11:43 PM	88133
0002	D	0123	@@200498044318	- 33.434208333333	-70.678175	12/6/2007 2:12:30 PM	>D00020123;@@200498044318;033260525;070406905;071206;171230<	12/6/2007 2:11:43 PM	88134
0002	D	0124	@@200498778718	- 33.434208333333	-70.678175	12/6/2007 2:12:30 PM	>D00020124;@@200498778718;033260525;070406905;071206;171230<	12/6/2007 2:11:43 PM	88135
0002	E	0000		0	0		>E0002;0012<	12/6/2007 2:11:43 PM	88136
0002	S	0000		0	0		>S0002<	12/6/2007 2:41:38 PM	88469
0002	D	0125	800446673778	- 33.434208333333	-70.678175	12/6/2007 2:12:30 PM	>D00020125;800446673778;033260525;070406905;071206;171230<	12/6/2007 2:41:38 PM	88470
0002	T	0126		- 33.434208333333	-70.678175	12/6/2007 2:12:30 PM	>T00020126;033260525;070406905;071206;171230<	12/6/2007 2:41:38 PM	88471
0002	D	0127	51200711300230379	- 33.434023333333	-70.67818	12/6/2007 2:15:15 PM	>D00020127;51200711300230379;033260414;070406908;071206;171515<	12/6/2007 2:41:38 PM	88472
0002	D	0128	80763046781	-33.433205	- 70.678461666667	12/6/2007 2:16:45 PM	>D00020128;80763046781;033259923;070407077;071206;171645<	12/6/2007 2:41:38 PM	88473
0002	T	0129		- 33.433161666667	- 70.678621666667	12/6/2007 2:17:45 PM	>T00020129;033259897;070407173;071206;171745<	12/6/2007 2:41:38 PM	88474
0002	D	0130	80760702335	-33.433315	- 70.677926666667	12/6/2007 2:18:45 PM	>D00020130;80760702335;033259989;070406756;071206;171845<	12/6/2007 2:41:38 PM	88475
0002	D	0131	80761039354	- 33.433348333333	- 70.677978333333	12/6/2007 2:19:30 PM	>D00020131;80761039354;033260009;070406787;071206;171930<	12/6/2007 2:41:38 PM	88476
0002	D	0132	00261568049543	- 33.433246666667	-70.677575	12/6/2007 2:20:30 PM	>D00020132;00261568049543;033259948;070406545;071206;172030<	12/6/2007 2:41:38 PM	88477
0002	D	0133	692007470209	- 33.433256666667	-70.67771	12/6/2007 2:21:45 PM	>D00020133;692007470209;033259954;070406626;071206;172145<	12/6/2007 2:41:38 PM	88478
0002	D	0134	@@2004946138XX	-	-70.67771	12/6/2007 2:21:45 PM	>D00020134;@@2004946138XX;0	12/6/2007	8847

				33.433256666667			33259954;070406626;071206;172145<	2:41:38 PM	9
0002	D	0135	80761482797	-33.433285	-70.678066666667	12/6/2007 2:22:45 PM	>D00020135;80761482797;033259971;070406840;071206;172245<	12/6/2007 2:41:38 PM	88480
0002	D	0136	80762006484	-33.433285	-70.678066666667	12/6/2007 2:22:45 PM	>D00020136;80762006484;033259971;070406840;071206;172245<	12/6/2007 2:41:38 PM	88481
0002	D	0137	@@200499197618	-33.433158333333	-70.678278333333	12/6/2007 2:23:45 PM	>D00020137;@@200499197618;033259895;070406967;071206;172345<	12/6/2007 2:41:38 PM	88482
0002	T	0138		-33.432276666667	-70.67846	12/6/2007 2:25:45 PM	>T00020138;033259366;070407076;071206;172545<	12/6/2007 2:41:38 PM	88483
0002	D	0139	@@200497624918	-33.432276666667	-70.67846	12/6/2007 2:25:45 PM	>D00020139;@@200497624918;033259366;070407076;071206;172545<	12/6/2007 2:41:38 PM	88484
0002	D	0140	80759504678	-33.432276666667	-70.67846	12/6/2007 2:25:45 PM	>D00020140;80759504678;033259366;070407076;071206;172545<	12/6/2007 2:41:38 PM	88485
0002	D	0141	80760746480	-33.431485	-70.678395	12/6/2007 2:28:00 PM	>D00020141;80760746480;033258891;070407037;071206;172800<	12/6/2007 2:41:38 PM	88486
0002	D	0142	689000394729	-33.431485	-70.678395	12/6/2007 2:28:00 PM	>D00020142;689000394729;033258891;070407037;071206;172800<	12/6/2007 2:41:38 PM	88487
0002	D	0143	51200711300238035	-33.4312	-70.678425	12/6/2007 2:29:00 PM	>D00020143;51200711300238035;033258720;070407055;071206;172900<	12/6/2007 2:41:38 PM	88488
0002	D	0144	80760413880	-33.4312	-70.678425	12/6/2007 2:29:00 PM	>D00020144;80760413880;033258720;070407055;071206;172900<	12/6/2007 2:41:38 PM	88489
0002	T	0145		-33.431121666667	-70.67858	12/6/2007 2:30:00 PM	>T00020145;033258673;070407148;071206;173000<	12/6/2007 2:41:38 PM	88490
0002	D	0146	80762908593	-33.431121666667	-70.67858	12/6/2007 2:30:00 PM	>D00020146;80762908593;033258673;070407148;071206;173000<	12/6/2007 2:41:38 PM	88491
0002	D	0147	80760303252	-33.431133333333	-70.678395	12/6/2007 2:31:00 PM	>D00020147;80760303252;033258680;070407037;071206;173100<	12/6/2007 2:41:38 PM	88492
0002	D	0148	80762178676	-33.431133333333	-70.678395	12/6/2007 2:31:00 PM	>D00020148;80762178676;033258680;070407037;071206;173100<	12/6/2007 2:41:38 PM	88493
0002	D	0149	@@200498092918	-33.431063333333	-70.678395	12/6/2007 2:32:30 PM	>D00020149;@@200498092918;033258638;070407037;071206;173230<	12/6/2007 2:41:38 PM	88494
0002	T	0150		-	-70.67848	12/6/2007 2:33:30 PM	>T00020150;033258425;0704070	12/6/2007	8849

				33.430708333333			88;071206;173330<	2:41:38 PM	5
0002	D	0151	80764275571	-33.430635	-70.678468333333	12/6/2007 2:33:45 PM	>D00020151;80764275571;033258381;070407081;071206;173345<	12/6/2007 2:41:38 PM	88496
0002	D	0152	51200712010194812	-33.430635	-70.678468333333	12/6/2007 2:33:45 PM	>D00020152;51200712010194812;033258381;070407081;071206;173345<	12/6/2007 2:41:38 PM	88497
0002	D	0153	@@200494265817	-33.430528333333	-70.678526666666	12/6/2007 2:35:00 PM	>D00020153;@@200494265817;033258317;070407116;071206;173500<	12/6/2007 2:41:38 PM	88498
0002	D	0154	51200711300241737	-33.430528333333	-70.678526666666	12/6/2007 2:35:00 PM	>D00020154;51200711300241737;033258317;070407116;071206;173500<	12/6/2007 2:41:38 PM	88499
0002	D	0155	80763303245	-33.430528333333	-70.678526666666	12/6/2007 2:35:00 PM	>D00020155;80763303245;033258317;070407116;071206;173500<	12/6/2007 2:41:38 PM	88500
0002	D	0156	51200712010201045	-33.430515	-70.678535	12/6/2007 2:35:15 PM	>D00020156;51200712010201045;033258309;070407121;071206;173515<	12/6/2007 2:41:38 PM	88501
0002	T	0157		-33.430433333333	-70.677825	12/6/2007 2:37:15 PM	>T00020157;033258260;070406695;071206;173715<	12/6/2007 2:41:38 PM	88502
0002	T	0158		-33.429766666666	-70.678625	12/6/2007 2:40:15 PM	>T00020158;033257860;070407175;071206;174015<	12/6/2007 2:41:38 PM	88503
0002	D	0159	692007451707	-33.429596666666	-70.678516666666	12/6/2007 2:41:15 PM	>D00020159;692007451707;033257758;070407110;071206;174115<	12/6/2007 2:41:38 PM	88504
0002	E	0000		0	0		>E0002;0037<	12/6/2007 2:41:38 PM	88505
0002	S	0000		0	0		>S0002<	12/6/2007 2:57:09 PM	88547
0002	D	0160	689000394780	-33.429608333333	-70.678603333333	12/6/2007 2:42:15 PM	>D00020160;689000394780;033257765;070407162;071206;174215<	12/6/2007 2:57:09 PM	88548
0002	D	0161	51200711300237500	-33.429608333333	-70.678603333333	12/6/2007 2:42:15 PM	>D00020161;51200711300237500;033257765;070407162;071206;174215<	12/6/2007 2:57:09 PM	88549
0002	T	0162		-33.42889	-70.678771666666	12/6/2007 2:44:00 PM	>T00020162;033257334;070407263;071206;174400<	12/6/2007 2:57:09 PM	88550
0002	D	0163	692007479455	-33.42889	-70.678771666666	12/6/2007 2:44:00 PM	>D00020163;692007479455;033257334;070407263;071206;174400<	12/6/2007 2:57:09 PM	88551
0002	D	0164	@@200496938318	-33.42889	-	12/6/2007 2:44:00 PM	>D00020164;@@200496938318;0	12/6/2007	8855

					70.67877166666 67		33257334;070407263;071206;174 400<	2:57:09 PM	2
0002	D	0165	80762218457	-33.428455	-70.679125	12/6/2007 2:45:00 PM	>D00020165;80762218457;03325 7073;070407475;071206;174500<	12/6/2007 2:57:09 PM	8855 3
0002	T	0166		- 33.42808666666 67	-70.67813	12/6/2007 2:48:00 PM	>T00020166;033256852;0704068 78;071206;174800<	12/6/2007 2:57:09 PM	8855 4
0002	D	0167	51200711300229222	- 33.42727333333 33	- 70.67808333333 33	12/6/2007 2:49:15 PM	>D00020167;51200711300229222 ;033256364;070406850;071206;1 74915<	12/6/2007 2:57:09 PM	8855 5
0002	D	0168	800446673779	- 33.42744833333 33	- 70.67810666666 67	12/6/2007 2:49:55 PM	>D00020168;800446673779;0332 56469;070406864;071206;174955 <	12/6/2007 2:57:09 PM	8855 6
0002	D	0169	692007434075	-33.427585	-70.67804	12/6/2007 2:51:31 PM	>D00020169;692007434075;0332 56551;070406824;071206;175131 <	12/6/2007 2:57:09 PM	8855 7
0002	D	0170	692007419714	-33.427585	-70.67804	12/6/2007 2:51:31 PM	>D00020170;692007419714;0332 56551;070406824;071206;175131 <	12/6/2007 2:57:09 PM	8855 8
0002	D	0171	@@200038387017	-33.427585	-70.67804	12/6/2007 2:51:45 PM	>D00020171;@@200038387017;0 33256551;070406824;071206;175 145<	12/6/2007 2:57:09 PM	8855 9
0002	T	0172		-33.42897	-70.67798	12/6/2007 2:52:45 PM	>T00020172;033257382;0704067 88;071206;175245<	12/6/2007 2:57:09 PM	8856 0
0002	D	0173	80763365496	-33.42897	-70.67798	12/6/2007 2:52:45 PM	>D00020173;80763365496;03325 7382;070406788;071206;175245<	12/6/2007 2:57:09 PM	8856 1
0002	D	0174	692007447128	- 33.42888833333 33	-70.67796	12/6/2007 2:53:00 PM	>D00020174;692007447128;0332 57333;070406776;071206;175300 <	12/6/2007 2:57:09 PM	8856 2
0002	D	0175	@@200499744218	- 33.42888833333 33	-70.67796	12/6/2007 2:53:00 PM	>D00020175;@@200499744218;0 33257333;070406776;071206;175 300<	12/6/2007 2:57:09 PM	8856 3
0002	D	0176	80762019047	-33.43021	-70.67753	12/6/2007 2:54:45 PM	>D00020176;80762019047;03325 8126;070406518;071206;175445<	12/6/2007 2:57:09 PM	8856 4
0002	D	0177	51200711300241354	-33.43012	- 70.67749833333 33	12/6/2007 2:55:45 PM	>D00020177;51200711300241354 ;033258072;070406499;071206;1 75545<	12/6/2007 2:57:09 PM	8856 5
0002	T	0178		- 33.43088833333 33	-70.677535	12/6/2007 2:57:53 PM	>T00020178;033258533;0704065 21;071206;175753<	12/6/2007 2:57:09 PM	8856 6
0002	E	0000		0	0		>E0002;0021<	12/6/2007 2:57:09 PM	8856 7
0002	S	0000		0	0		>S0002<	12/6/2007	8878

								3:13:23 PM	3
0002	D	0179	0711296152902502903198	-33.430888333333	-70.677535	12/6/2007 2:57:53 PM	>D00020179;0711296152902502903198;033258533;070406521;071206;175753<	12/6/2007 3:13:23 PM	88784
0002	D	0180	51200712010195134	-33.430878333333	-70.677516666667	12/6/2007 2:59:30 PM	>D00020180;51200712010195134;033258527;070406510;071206;175930<	12/6/2007 3:13:23 PM	88785
0002	T	0181		-33.431285	-70.677531666667	12/6/2007 3:02:30 PM	>T00020181;033258771;070406519;071206;180230<	12/6/2007 3:13:23 PM	88786
0002	D	0182	80761113333	-33.43192	-70.677401666667	12/6/2007 3:05:15 PM	>D00020182;80761113333;033259152;070406441;071206;180515<	12/6/2007 3:13:23 PM	88787
0002	T	0183		-33.43189	-70.677388333333	12/6/2007 3:06:00 PM	>T00020183;033259134;070406433;071206;180600<	12/6/2007 3:13:23 PM	88788
0002	D	0184	80763474120	-33.431638333333	-70.677331666667	12/6/2007 3:06:45 PM	>D00020184;80763474120;033258983;070406399;071206;180645<	12/6/2007 3:13:23 PM	88789
0002	D	0185	692007446997	-33.433225	-70.677483333333	12/6/2007 3:08:15 PM	>D00020185;692007446997;033259935;070406490;071206;180815<	12/6/2007 3:13:23 PM	88790
0002	D	0186	51200711300236474	-33.433231666667	-70.677203333333	12/6/2007 3:09:15 PM	>D00020186;51200711300236474;033259939;070406322;071206;180915<	12/6/2007 3:13:23 PM	88791
0002	D	0187	51200711300237861	-33.433253333333	-70.677255	12/6/2007 3:09:45 PM	>D00020187;51200711300237861;033259952;070406353;071206;180945<	12/6/2007 3:13:23 PM	88792
0002	D	0188	692007423995	-33.433345	-70.677395	12/6/2007 3:10:30 PM	>D00020188;692007423995;033260007;070406437;071206;181030<	12/6/2007 3:13:23 PM	88793
0002	D	0189	80759204755	-33.433345	-70.677395	12/6/2007 3:10:30 PM	>D00020189;80759204755;033260007;070406437;071206;181030<	12/6/2007 3:13:23 PM	88794
0002	D	0190	51200712010199369	-33.43347	-70.677528333333	12/6/2007 3:11:00 PM	>D00020190;51200712010199369;033260082;070406517;071206;181100<	12/6/2007 3:13:23 PM	88795
0002	T	0191		-33.433771666667	-70.677263333333	12/6/2007 3:12:00 PM	>T00020191;033260263;070406358;071206;181200<	12/6/2007 3:13:23 PM	88796
0002	D	0192	@@200498651318	-33.434963333333	-70.677235	12/6/2007 3:12:49 PM	>D00020192;@@200498651318;033260978;070406341;071206;181249<	12/6/2007 3:13:23 PM	88797
0002	E	0000		0	0		>E0002;0016<	12/6/2007 3:13:23 PM	88798
0002	S	0000		0	0		>S0002<	12/6/2007	8887

								3:25:26 PM	1
0002	D	0193	80760298992	- 33.43498833333	- 70.67726833333	12/6/2007 3:13:59 PM	>D00020193;80760298992;033260993;070406361;071206;181359<	12/6/2007 3:25:26 PM	8887 2
0002	D	0194	80762074277	- 33.43498833333	- 70.67726833333	12/6/2007 3:13:59 PM	>D00020194;80762074277;033260993;070406361;071206;181359<	12/6/2007 3:25:26 PM	8887 3
0002	T	0195		- 33.43498833333	- 70.67726833333	12/6/2007 3:16:15 PM	>T00020195;033260993;070406361;071206;181615<	12/6/2007 3:25:26 PM	8887 4
0002	T	0196		- 33.43664833333	-70.67685	12/6/2007 3:19:00 PM	>T00020196;033261989;070406110;071206;181900<	12/6/2007 3:25:26 PM	8887 5
0002	D	0197	692007433394	- 33.43753833333	- 70.67676833333	12/6/2007 3:20:45 PM	>D00020197;692007433394;033262523;070406061;071206;182045<	12/6/2007 3:25:26 PM	8887 6
0002	T	0198		-33.437625	-70.67693	12/6/2007 3:22:32 PM	>T00020198;033262575;070406158;071206;182232<	12/6/2007 3:25:26 PM	8887 7
0002	D	0199	80764106060	- 33.43790833333	- 70.67689666666	12/6/2007 3:24:15 PM	>D00020199;80764106060;033262745;070406138;071206;182415<	12/6/2007 3:25:26 PM	8887 8
0002	D	0200	@@200038024117	-33.43791	-70.676895	12/6/2007 3:24:30 PM	>D00020200;@@200038024117;033262746;070406137;071206;182430<	12/6/2007 3:25:26 PM	8887 9
0002	E	0000		0	0		>E0002;0010<	12/6/2007 3:25:26 PM	8888 0
0002	S	0000		0	0		>S0002<	12/6/2007 3:34:50 PM	8899 1
0002	T	0201		- 33.43796333333	- 70.67688166666	12/6/2007 3:25:30 PM	>T00020201;033262778;070406129;071206;182530<	12/6/2007 3:34:50 PM	8899 2
0002	T	0202		-33.43793	- 70.67595333333	12/6/2007 3:30:30 PM	>T00020202;033262758;070405572;071206;183030<	12/6/2007 3:34:50 PM	8899 3
0002	T	0203		- 33.43782666666	- 70.67582666666	12/6/2007 3:33:34 PM	>T00020203;033262696;070405496;071206;183334<	12/6/2007 3:34:50 PM	8899 4
0002	E	0000		0	0		>E0002;0005<	12/6/2007 3:34:50 PM	8899 5
0002	S	0000		0	0		>S0002<	12/6/2007 3:44:50 PM	8900 6
0002	T	0204		-	-	12/6/2007 3:35:32 PM	>T00020204;033262579;0704054	12/6/2007	8900

				33.43763166666 67	70.67578666666 67		72;071206;183532<	3:44:50 PM	7
0002	T	0205		- 33.43674666666 67	-70.67622	12/6/2007 3:39:30 PM	>T00020205;033262048;0704057 32;071206;183930<	12/6/2007 3:44:50 PM	8900 8
0002	T	0206		-33.435645	-70.67598	12/6/2007 3:42:30 PM	>T00020206;033261387;0704055 88;071206;184230<	12/6/2007 3:44:50 PM	8900 9
0002	E	0000		0	0		>E0002;0005<	12/6/2007 3:44:50 PM	8901 0
0002	S	0000		0	0		>S0002<	12/6/2007 3:54:53 PM	8912 1
0002	T	0207		- 33.43464666666 67	- 70.67622666666 67	12/6/2007 3:45:30 PM	>T00020207;033260788;0704057 36;071206;184530<	12/6/2007 3:54:53 PM	8912 2
0002	T	0208		- 33.43338166666 67	- 70.67618833333 33	12/6/2007 3:49:30 PM	>T00020208;033260029;0704057 13;071206;184930<	12/6/2007 3:54:53 PM	8912 3
0002	T	0209		- 33.43290833333 33	- 70.67636666666 67	12/6/2007 3:52:30 PM	>T00020209;033259745;0704058 20;071206;185230<	12/6/2007 3:54:53 PM	8912 4
0002	E	0000		0	0		>E0002;0005<	12/6/2007 3:54:53 PM	8912 5
0002	S	0000		0	0		>S0002<	12/6/2007 4:04:53 PM	8914 3
0002	T	0210		- 33.43215666666 67	-70.67636	12/6/2007 3:55:30 PM	>T00020210;033259294;0704058 16;071206;185530<	12/6/2007 4:04:53 PM	8914 4
0002	T	0211		-33.43233	-70.676415	12/6/2007 3:59:39 PM	>T00020211;033259398;0704058 49;071206;185939<	12/6/2007 4:04:53 PM	8914 5
0002	T	0212		-33.431325	- 70.67653833333 33	12/6/2007 4:02:30 PM	>T00020212;033258795;0704059 23;071206;190230<	12/6/2007 4:04:53 PM	8914 6
0002	E	0000		0	0		>E0002;0005<	12/6/2007 4:04:53 PM	8914 7
0002	S	0000		0	0		>S0002<	12/6/2007 4:14:55 PM	8919 0
0002	T	0213		-33.430175	-70.67652	12/6/2007 4:05:15 PM	>T00020213;033258105;0704059 12;071206;190515<	12/6/2007 4:14:55 PM	8919 1
0002	T	0214		-	-70.676745	12/6/2007 4:09:30 PM	>T00020214;033258031;0704060	12/6/2007	8919

				33.430051666667			47;071206;190930<	4:14:55 PM	2
0002	T	0215		-33.429698333333	-70.676576666667	12/6/2007 4:12:15 PM	>T00020215;033257819;070405946;071206;191215<	12/6/2007 4:14:55 PM	89193
0002	T	0216		-33.427936666667	-70.676721666667	12/6/2007 4:15:45 PM	>T00020216;033256762;070406033;071206;191545<	12/6/2007 4:14:55 PM	89194
0002	E	0000		0	0		>E0002;0006<	12/6/2007 4:14:55 PM	89195
0002	S	0000		0	0		>S0002<	12/6/2007 4:24:57 PM	89263
0002	T	0217		-33.427333333333	-70.676598333333	12/6/2007 4:18:38 PM	>T00020217;033256400;070405959;071206;191838<	12/6/2007 4:24:57 PM	89264
0002	T	0218		-33.427155	-70.67521	12/6/2007 4:21:40 PM	>T00020218;033256293;070405126;071206;192140<	12/6/2007 4:24:57 PM	89265
0002	T	0219		-33.428275	-70.675258333333	12/6/2007 4:24:45 PM	>T00020219;033256965;070405155;071206;192445<	12/6/2007 4:24:57 PM	89266
0002	E	0000		0	0		>E0002;0005<	12/6/2007 4:24:57 PM	89267
0002	S	0000		0	0		>S0002<	12/6/2007 4:34:57 PM	89329
0002	T	0220		-33.428203333333	-70.674903333333	12/6/2007 4:27:35 PM	>T00020220;033256922;070404942;071206;192735<	12/6/2007 4:34:57 PM	89330
0002	T	0221		-33.429796666667	-70.675103333333	12/6/2007 4:30:46 PM	>T00020221;033257878;070405062;071206;193046<	12/6/2007 4:34:57 PM	89331
0002	T	0222		-33.430063333333	-70.675053333333	12/6/2007 4:33:45 PM	>T00020222;033258038;070405032;071206;193345<	12/6/2007 4:34:57 PM	89332
0002	E	0000		0	0		>E0002;0005<	12/6/2007 4:34:57 PM	89333
0002	S	0000		0	0		>S0002<	12/6/2007 4:44:58 PM	89349
0002	T	0223		-33.430405	-70.675148333333	12/6/2007 4:35:45 PM	>T00020223;033258243;070405089;071206;193545<	12/6/2007 4:44:58 PM	89350
0002	T	0224		-33.431705	-	12/6/2007 4:39:45 PM	>T00020224;033259023;0704050	12/6/2007	8935

					70.67512666666 67		76;071206;193945<	4:44:58 PM	1
0002	T	0225		- 33.43251333333	- 70.67463166666 67	12/6/2007 4:42:45 PM	>T00020225;033259508;0704047 79;071206;194245<	12/6/2007 4:44:58 PM	8935 2
0002	E	0000		0	0		>E0002;0005<	12/6/2007 4:44:58 PM	8935 3
0002	S	0000		0	0		>S0002<	12/6/2007 4:54:58 PM	8938 2
0002	T	0226		- 33.43236833333	- 70.67483833333 33	12/6/2007 4:45:45 PM	>T00020226;033259421;0704049 03;071206;194545<	12/6/2007 4:54:58 PM	8938 3
0002	T	0227		- 33.43256833333	- 70.67475166666 67	12/6/2007 4:49:45 PM	>T00020227;033259541;0704048 51;071206;194945<	12/6/2007 4:54:58 PM	8938 4
0002	T	0228		-33.43257	- 70.67472333333 33	12/6/2007 4:52:45 PM	>T00020228;033259542;0704048 34;071206;195245<	12/6/2007 4:54:58 PM	8938 5
0002	E	0000		0	0		>E0002;0005<	12/6/2007 4:54:58 PM	8938 6
0002	S	0000		0	0		>S0002<	12/6/2007 5:05:00 PM	8945 6
0002	T	0229		- 33.43205666666 67	-70.67526	12/6/2007 4:55:45 PM	>T00020229;033259234;0704051 56;071206;195545<	12/6/2007 5:05:00 PM	8945 7
0002	T	0230		- 33.43206833333	- 70.67532666666 67	12/6/2007 4:59:45 PM	>T00020230;033259241;0704051 96;071206;195945<	12/6/2007 5:05:00 PM	8945 8
0002	T	0231		- 33.43175333333	- 70.67453333333 33	12/6/2007 5:02:45 PM	>T00020231;033259052;0704047 20;071206;200245<	12/6/2007 5:05:00 PM	8945 9
0002	E	0000		0	0		>E0002;0005<	12/6/2007 5:05:00 PM	8946 0
0002	S	0000		0	0		>S0002<	12/6/2007 5:15:03 PM	8954 0
0002	T	0232		-33.42949	- 70.67415333333 33	12/6/2007 5:05:45 PM	>T00020232;033257694;0704044 92;071206;200545<	12/6/2007 5:15:03 PM	8954 1
0002	T	0233		-33.430155	- 70.67422166666 67	12/6/2007 5:09:45 PM	>T00020233;033258093;0704045 33;071206;200945<	12/6/2007 5:15:03 PM	8954 2
0002	T	0234		-	-	12/6/2007 5:12:45 PM	>T00020234;033258755;0704044	12/6/2007	8954

				33.431258333333	70.674143333333		86;071206;201245<	5:15:03 PM	3
0002	E	0000		0	0		>E0002;0005<	12/6/2007 5:15:03 PM	89544
0002	S	0000		0	0		>S0002<	12/6/2007 5:25:01 PM	89660
0002	T	0235		-33.432205	- 70.673876666667	12/6/2007 5:15:45 PM	>T00020235;033259323;070404326;071206;201545<	12/6/2007 5:25:01 PM	89661
0002	T	0236		- 33.435113333333	- 70.673798333333	12/6/2007 5:19:47 PM	>T00020236;033261068;070404279;071206;201947<	12/6/2007 5:25:01 PM	89662
0002	T	0237		- 33.435508333333	- 70.673673333333	12/6/2007 5:22:45 PM	>T00020237;033261305;070404204;071206;202245<	12/6/2007 5:25:01 PM	89663
0002	E	0000		0	0		>E0002;0005<	12/6/2007 5:25:01 PM	89664
0002	S	0000		0	0		>S0002<	12/6/2007 5:35:04 PM	89742
0002	T	0238		- 33.437028333333	-70.67357	12/6/2007 5:25:45 PM	>T00020238;033262217;070404142;071206;202545<	12/6/2007 5:35:04 PM	89743
0002	T	0239		-33.437265	- 70.672668333333	12/6/2007 5:29:45 PM	>T00020239;033262359;070403601;071206;202945<	12/6/2007 5:35:04 PM	89744
0002	T	0240		- 33.436668333333	-70.67279	12/6/2007 5:32:45 PM	>T00020240;033262001;070403674;071206;203245<	12/6/2007 5:35:04 PM	89745
0002	E	0000		0	0		>E0002;0005<	12/6/2007 5:35:04 PM	89746
0002	S	0000		0	0		>S0002<	12/6/2007 5:45:07 PM	89795
0002	T	0241		-33.435785	- 70.672776666667	12/6/2007 5:35:48 PM	>T00020241;033261471;070403666;071206;203548<	12/6/2007 5:45:07 PM	89796
0002	T	0242		-33.43568	- 70.672768333333	12/6/2007 5:39:34 PM	>T00020242;033261408;070403661;071206;203934<	12/6/2007 5:45:07 PM	89797
0002	T	0243		-33.433545	- 70.673101666667	12/6/2007 5:42:51 PM	>T00020243;033260127;070403861;071206;204251<	12/6/2007 5:45:07 PM	89798
0002	E	0000		0	0		>E0002;0005<	12/6/2007	8979

								5:45:07 PM	9
0002	S	0000		0	0		>S0002<	12/6/2007 5:55:08 PM	89867
0002	T	0244		-33.432513333333	-70.6731116666667	12/6/2007 5:45:45 PM	>T00020244;033259508;070403867;071206;204545<	12/6/2007 5:55:08 PM	89868
0002	T	0245		-33.4325416666667	-70.67312	12/6/2007 5:49:51 PM	>T00020245;033259525;070403872;071206;204951<	12/6/2007 5:55:08 PM	89869
0002	T	0246		-33.43224	-70.67285	12/6/2007 5:52:45 PM	>T00020246;033259344;070403710;071206;205245<	12/6/2007 5:55:08 PM	89870
0002	E	0000		0	0		>E0002;0005<	12/6/2007 5:55:08 PM	89871
0002	S	0000		0	0		>S0002<	12/6/2007 6:05:14 PM	89969
0002	T	0247		-33.4320316666667	-70.6730533333333	12/6/2007 5:55:48 PM	>T00020247;033259219;070403832;071206;205548<	12/6/2007 6:05:14 PM	89970
0002	T	0248		-33.4311866666667	-70.67287	12/6/2007 5:59:46 PM	>T00020248;033258712;070403722;071206;205946<	12/6/2007 6:05:14 PM	89971
0002	T	0249		-33.4313033333333	-70.673225	12/6/2007 6:02:49 PM	>T00020249;033258782;070403935;071206;210249<	12/6/2007 6:05:14 PM	89972
0002	E	0000		0	0		>E0002;0005<	12/6/2007 6:05:14 PM	89973
0002	S	0000		0	0		>S0002<	12/6/2007 6:15:10 PM	90075
0002	T	0250		-33.42979	-70.673375	12/6/2007 6:05:45 PM	>T00020250;033257874;070404025;071206;210545<	12/6/2007 6:15:10 PM	90076
0002	T	0251		-33.4341933333333	-70.6722116666667	12/6/2007 6:09:46 PM	>T00020251;033260516;070403327;071206;210946<	12/6/2007 6:15:10 PM	90077
0002	T	0252		-33.4357833333333	-70.6719783333333	12/6/2007 6:12:50 PM	>T00020252;033261470;070403187;071206;211250<	12/6/2007 6:15:10 PM	90078
0002	E	0000		0	0		>E0002;0005<	12/6/2007 6:15:10 PM	90079
0002	S	0000		0	0		>S0002<	12/6/2007	9014

								6:25:10 PM	4
0002	T	0253		-33.43531	-70.67118	12/6/2007 6:15:45 PM	>T00020253;033261186;070402708;071206;211545<	12/6/2007 6:25:10 PM	90145
0002	T	0254		-33.437858333333	-70.67207	12/6/2007 6:19:54 PM	>T00020254;033262715;070403242;071206;211954<	12/6/2007 6:25:10 PM	90146
0002	T	0255		-33.437468333333	-70.674096666667	12/6/2007 6:22:45 PM	>T00020255;033262481;070404458;071206;212245<	12/6/2007 6:25:10 PM	90147
0002	E	0000		0	0		>E0002;0005<	12/6/2007 6:25:10 PM	90148
0002	S	0000		0	0		>S0002<	12/6/2007 6:35:49 PM	90223
0002	T	0256		-33.437473333333	-70.674135	12/6/2007 6:26:00 PM	>T00020256;033262484;070404481;071206;212600<	12/6/2007 6:35:49 PM	90224
0002	T	0257		-33.437483333333	-70.674193333333	12/6/2007 6:30:00 PM	>T00020257;033262490;070404516;071206;213000<	12/6/2007 6:35:49 PM	90225
0002	T	0258		-33.437993333333	-70.67439	12/6/2007 6:32:59 PM	>T00020258;033262796;070404634;071206;213259<	12/6/2007 6:35:49 PM	90226
0002	E	0000		0	0		>E0002;0005<	12/6/2007 6:35:49 PM	90227
0002	S	0000		0	0		>S0002<	12/6/2007 6:45:13 PM	90238
0002	T	0259		-33.437441666667	-70.673691666667	12/6/2007 6:36:00 PM	>T00020259;033262465;070404215;071206;213600<	12/6/2007 6:45:13 PM	90239
0002	T	0260		-33.43682	-70.672055	12/6/2007 6:40:00 PM	>T00020260;033262092;070403233;071206;214000<	12/6/2007 6:45:13 PM	90240
0002	T	0261		-33.436155	-70.663473333333	12/6/2007 6:42:56 PM	>T00020261;033261693;070398084;071206;214256<	12/6/2007 6:45:13 PM	90241
0002	E	0000		0	0		>E0002;0005<	12/6/2007 6:45:13 PM	90242
0002	S	0000		0	0		>S0002<	12/6/2007 6:55:13 PM	90356
0002	T	0262		-33.43566	-	12/6/2007 6:45:50 PM	>T00020262;033261396;0703934	12/6/2007	9035

					70.655748333333		49;071206;214550<	6:55:13 PM	7
0002	T	0263		-33.43566	- 70.655748333333	12/6/2007 6:49:51 PM	>T00020263;033261396;0703934 49;071206;214951<	12/6/2007 6:55:13 PM	9035 8
0002	T	0264		-33.43566	- 70.655748333333	12/6/2007 6:52:54 PM	>T00020264;033261396;0703934 49;071206;215254<	12/6/2007 6:55:13 PM	9035 9
0002	T	0265		-33.43566	- 70.655748333333	12/6/2007 6:55:57 PM	>T00020265;033261396;0703934 49;071206;215557<	12/6/2007 6:55:13 PM	9036 0
0002	E	0000		0	0		>E0002;0006<	12/6/2007 6:55:13 PM	9036 1
0002	S	0000		0	0		>S0002<	12/6/2007 7:05:42 PM	9038 7
0002	T	0266		-33.43566	- 70.655748333333	12/6/2007 6:59:00 PM	>T00020266;033261396;0703934 49;071206;215900<	12/6/2007 7:05:42 PM	9038 8
0002	T	0267		-33.438235	- 70.658306666666 67	12/6/2007 7:02:03 PM	>T00020267;033262941;0703949 84;071206;220203<	12/6/2007 7:05:42 PM	9038 9
0002	T	0268		-33.438235	- 70.658306666666 67	12/6/2007 7:04:51 PM	>T00020268;033262941;0703949 84;071206;220451<	12/6/2007 7:05:42 PM	9039 0
0002	E	0000		0	0		>E0002;0005<	12/6/2007 7:05:42 PM	9039 1
0002	S	0000		0	0		>S0002<	12/6/2007 7:15:14 PM	9045 8
0002	T	0269		-33.438235	- 70.658306666666 67	12/6/2007 7:06:02 PM	>T00020269;033262941;0703949 84;071206;220602<	12/6/2007 7:15:14 PM	9045 9
0002	T	0270		-33.438235	- 70.658306666666 67	12/6/2007 7:10:54 PM	>T00020270;033262941;0703949 84;071206;221054<	12/6/2007 7:15:14 PM	9046 0
0002	T	0271		-33.438235	- 70.658306666666 67	12/6/2007 7:13:57 PM	>T00020271;033262941;0703949 84;071206;221357<	12/6/2007 7:15:14 PM	9046 1
0002	E	0000		0	0		>E0002;0005<	12/6/2007 7:15:14 PM	9046 2
0002	S	0000		0	0		>S0002<	12/6/2007 7:25:30 PM	9047 8
0002	T	0272		-33.438235	-	12/6/2007 7:16:04 PM	>T00020272;033262941;0703949	12/6/2007	9047

					70.658306666667		84;071206;221604<	7:25:30 PM	9
0002	T	0273		-33.438235	- 70.658306666667	12/6/2007 7:19:58 PM	>T00020273;033262941;0703949 84;071206;221958<	12/6/2007 7:25:30 PM	9048 0
0002	T	0274		- 33.477396666667	- 70.622358333333	12/6/2007 7:23:01 PM	>T00020274;033286438;0703734 15;071206;222301<	12/6/2007 7:25:30 PM	9048 1
0002	E	0000		0	0		>E0002;0005<	12/6/2007 7:25:30 PM	9048 2
0002	S	0000		0	0		>S0002<	12/6/2007 7:35:21 PM	9050 7
0002	T	0275		- 33.491896666667	-70.61744	12/6/2007 7:26:00 PM	>T00020275;033295138;0703704 64;071206;222600<	12/6/2007 7:35:21 PM	9050 8
0002	T	0276		- 33.490083333333	- 70.611571666667	12/6/2007 7:30:01 PM	>T00020276;033294050;0703669 43;071206;223001<	12/6/2007 7:35:21 PM	9050 9
0002	T	0277		- 33.488403333333	-70.611005	12/6/2007 7:33:00 PM	>T00020277;033293042;0703666 03;071206;223300<	12/6/2007 7:35:21 PM	9051 0
0002	T	0278		- 33.487326666667	- 70.611406666667	12/6/2007 7:36:00 PM	>T00020278;033292396;0703668 44;071206;223600<	12/6/2007 7:35:21 PM	9051 1
0002	E	0000		0	0		>E0002;0006<	12/6/2007 7:35:21 PM	9051 2