

Pruebas GPS 13-08-2007

ID GPS	Tipo	Corr.	Código de Barras	Latitud	Longitud	Fecha/Hora/GMT GPS	String ORG.	Fecha/Sistema	LINK
1234	SOT			0	0		SOT;1234	8/13/2007 5:55:32 AM	15206
0008	PUP	0000	7802600133217	0	0	8/13/2007 5:55:32 AM	PUP;0000;7802600133217;Firmware v1.2egps, Aug 2 2007	8/13/2007 5:55:32 AM	15207
1234	EOT			0	0		EOT;1234;000084	8/13/2007 5:55:32 AM	15208
1234	SOT			0	0		SOT;1234	8/13/2007 6:01:32 AM	15209
0008	TRK	0001		-33.5169033333333	70.7030933333333	6:01:33 AM	TRK;0001;-03331.0142;+07042.1856;070813;100650	8/13/2007	15210
0008	TRK	0002		-33.5166133333333	70.7035466666667	6:01:33 AM	TRK;0002;-03330.9968;+07042.2128;070813;100845	8/13/2007	15211
1234	EOT			0	0		EOT;1234;000125	8/13/2007 6:01:33 AM	15212
1234	SOT			0	0		SOT;1234	8/13/2007 6:06:38 AM	15213
0008	TRK	0003		-33.516655	70.7034316666667	6:06:38 AM	TRK;0003;-03330.9993;+07042.2059;070813;101045	8/13/2007	15214
0008	TRK	0004		-33.5167716666667	70.7032633333333	6:06:38 AM	TRK;0004;-03331.0063;+07042.1958;070813;101245	8/13/2007	15215
0008	TRK	0005		-33.5167816666667	70.7032883333333	6:06:38 AM	TRK;0005;-03331.0069;+07042.1973;070813;101456	8/13/2007	15216
1234	EOT			0	0		EOT;1234;000173	8/13/2007 6:06:38 AM	15217
1234	SOT			0	0		SOT;1234	8/13/2007 6:11:37 AM	15218
0008	TRK	0006		-33.516775	70.7031366666667	6:11:37 AM	TRK;0006;-03331.0065;+07042.1882;070813;101645	8/13/2007	15219
0008	TRK	0007		-33.513995	70.7062583333333	6:11:37 AM	TRK;0007;-03330.8397;+07042.3755;070813;101845	8/13/2007	15220
1234	EOT			0	0		EOT;1234;000125	8/13/2007 6:11:37 AM	15221
1234	SOT			0	0		SOT;1234	8/13/2007 6:16:35 AM	15222
0008	TRK	0008		-33.5113133333333	70.6990133333333	6:16:36 AM	TRK;0008;-03330.6788;+07041.9408;070813;102045	8/13/2007	15223
0008	TRK	0009		-33.5171516666667	70.7042816666667	6:16:36 AM	TRK;0009;-03331.0291;+07042.2569;070813;102245	8/13/2007	15224
0008	TRK	0010		-33.5155716666667	70.7087633333333	6:16:36 AM	TRK;0010;-03330.9343;+07042.5258;070813;102500	8/13/2007	15225
1234	EOT			0	0		EOT;1234;000173	8/13/2007 6:16:36 AM	15226
1234	SOT			0	0		SOT;1234	8/13/2007 6:21:35 AM	15227
0008	TRK	0011		-33.5106133333333	-70.69913	6:21:36 AM	TRK;0011;-03330.6368;+07041.9478;070813;102645	8/13/2007	15228
0008	TRK	0012		-	-70.68641	6:21:36 AM	TRK;0012;-	8/13/2007	15229

				33.4829066666667			03328.9744;+07041.1846;070813;102845		
1234	EOT			0	0		EOT;1234;000125	8/13/2007 6:21:36 AM	15230
1234	SOT			0	0		SOT;1234	8/13/2007 6:26:34 AM	15231
0008	TRK	0013		-33.478825	-70.663615	6:26:35 AM	TRK;0013;- 03328.7295;+07039.8169;070813;103045	8/13/2007	15232
0008	TRK	0014		-33.480125	-70.64618	6:26:35 AM	TRK;0014;- 03328.8075;+07038.7708;070813;103245	8/13/2007	15233
0008	TRK	0015		- 33.4875033333333	- 70.6186383333333	6:26:35 AM	TRK;0015;- 03329.2502;+07037.1183;070813;103500	8/13/2007	15234
1234	EOT			0	0		EOT;1234;000173	8/13/2007 6:26:35 AM	15235
1234	SOT			0	0		SOT;1234	8/13/2007 6:31:36 AM	15236
0008	TRK	0016		- 33.4879483333333	- 70.6114883333333	6:31:37 AM	TRK;0016;- 03329.2769;+07036.6893;070813;103645	8/13/2007	15237
0008	TRK	0017		-33.48835	-70.61131	6:31:37 AM	TRK;0017;- 03329.3010;+07036.6786;070813;103850	8/13/2007	15238
1234	EOT			0	0		EOT;1234;000125	8/13/2007 6:31:37 AM	15239
1234	SOT			0	0		SOT;1234	8/13/2007 6:36:48 AM	15240
0008	TRK	0018		-33.48835	-70.61131	6:36:49 AM	TRK;0018;- 03329.3010;+07036.6786;070813;104056	8/13/2007	15241
0008	TRK	0019		-33.48835	-70.61131	6:36:49 AM	TRK;0019;- 03329.3010;+07036.6786;070813;104249	8/13/2007	15242
0008	TRK	0020		-33.48835	-70.61131	6:36:49 AM	TRK;0020;- 03329.3010;+07036.6786;070813;104509	8/13/2007	15243
1234	EOT			0	0		EOT;1234;000173	8/13/2007 6:36:49 AM	15244
1234	SOT			0	0		SOT;1234	8/13/2007 6:41:36 AM	15245
0008	TRK	0021		-33.48835	-70.61131	6:41:37 AM	TRK;0021;- 03329.3010;+07036.6786;070813;104648	8/13/2007	15246
0008	TRK	0022		-33.48835	-70.61131	6:41:38 AM	TRK;0022;- 03329.3010;+07036.6786;070813;104854	8/13/2007	15247
1234	EOT			0	0		EOT;1234;000125	8/13/2007 6:41:38 AM	15248
1234	SOT			0	0		SOT;1234	8/13/2007 6:46:38 AM	15249
0008	TRK	0023		-33.48835	-70.61131	6:46:38 AM	TRK;0023;- 03329.3010;+07036.6786;070813;105047	8/13/2007	15250
0008	TRK	0024		-33.48835	-70.61131	6:46:38 AM	TRK;0024;- 03329.3010;+07036.6786;070813;105253	8/13/2007	15251
0008	TRK	0025		-33.48835	-70.61131	6:46:38 AM	TRK;0025;- 03329.3010;+07036.6786;070813;105500	8/13/2007	15252
1234	EOT			0	0		EOT;1234;000173	8/13/2007 6:46:38 AM	15253
1234	SOT			0	0		SOT;1234	8/13/2007 6:51:38 AM	15254

0008	TRK	0026		-33.48835	-70.61131	6:51:38 AM	TRK;0026;- 03329.3010;+07036.6786;070813;105652	8/13/2007	15255
0008	TRK	0027		-33.48835	-70.61131	6:51:38 AM	TRK;0027;- 03329.3010;+07036.6786;070813;105845	8/13/2007	15256
1234	EOT			0	0		EOT;1234;000125	8/13/2007 6:51:38 AM	15257
1234	SOT			0	0		SOT;1234	8/13/2007 6:56:38 AM	15258
0008	TRK	0028		-33.48835	-70.61131	6:56:39 AM	TRK;0028;- 03329.3010;+07036.6786;070813;110051	8/13/2007	15259
0008	TRK	0029		-33.48835	-70.61131	6:56:39 AM	TRK;0029;- 03329.3010;+07036.6786;070813;110258	8/13/2007	15260
0008	TRK	0030		-33.48835	-70.61131	6:56:39 AM	TRK;0030;- 03329.3010;+07036.6786;070813;110504	8/13/2007	15261
1234	EOT			0	0		EOT;1234;000173	8/13/2007 6:56:39 AM	15262
1234	SOT			0	0		SOT;1234	8/13/2007 7:01:39 AM	15263
0008	TRK	0031		-33.48835	-70.61131	7:01:39 AM	TRK;0031;- 03329.3010;+07036.6786;070813;110657	8/13/2007	15264
0008	TRK	0032		-33.48835	-70.61131	7:01:39 AM	TRK;0032;- 03329.3010;+07036.6786;070813;110849	8/13/2007	15265
1234	EOT			0	0		EOT;1234;000125	8/13/2007 7:01:39 AM	15266
1234	SOT			0	0		SOT;1234	8/13/2007 7:06:39 AM	15267
0008	TRK	0033		-33.48835	-70.61131	7:06:40 AM	TRK;0033;- 03329.3010;+07036.6786;070813;111056	8/13/2007	15268
0008	TRK	0034		-33.48835	-70.61131	7:06:40 AM	TRK;0034;- 03329.3010;+07036.6786;070813;111248	8/13/2007	15269
0008	TRK	0035		-33.48835	-70.61131	7:06:40 AM	TRK;0035;- 03329.3010;+07036.6786;070813;111509	8/13/2007	15270
1234	EOT			0	0		EOT;1234;000173	8/13/2007 7:06:40 AM	15271
1234	SOT			0	0		SOT;1234	8/13/2007 7:11:40 AM	15272
0008	TRK	0036		-33.48835	-70.61131	7:11:40 AM	TRK;0036;- 03329.3010;+07036.6786;070813;111647	8/13/2007	15273
0008	TRK	0037		-33.48835	-70.61131	7:11:41 AM	TRK;0037;- 03329.3010;+07036.6786;070813;111854	8/13/2007	15274
1234	EOT			0	0		EOT;1234;000125	8/13/2007 7:11:41 AM	15275
1234	SOT			0	0		SOT;1234	8/13/2007 7:16:41 AM	15276
0008	TRK	0038		-33.48835	-70.61131	7:16:42 AM	TRK;0038;- 03329.3010;+07036.6786;070813;112100	8/13/2007	15277
0008	TRK	0039		-33.48835	-70.61131	7:16:42 AM	TRK;0039;- 03329.3010;+07036.6786;070813;112253	8/13/2007	15278
0008	TRK	0040		-33.48835	-70.61131	7:16:42 AM	TRK;0040;- 03329.3010;+07036.6786;070813;112513	8/13/2007	15279
1234	EOT			0	0		EOT;1234;000173	8/13/2007	15280

								7:16:42 AM	
1234	SOT			0	0		SOT;1234	8/13/2007 7:21:42 AM	15281
0008	TRK	0041		-33.48835	-70.61131	7:21:43 AM	TRK;0041;- 03329.3010;+07036.6786;070813;112652	8/13/2007	15282
0008	TRK	0042		-33.48835	-70.61131	7:21:43 AM	TRK;0042;- 03329.3010;+07036.6786;070813;112858	8/13/2007	15283
1234	EOT			0	0		EOT;1234;000125	8/13/2007 7:21:43 AM	15284
1234	SOT			0	0		SOT;1234	8/13/2007 7:26:42 AM	15285
0008	TRK	0043		-33.48835	-70.61131	7:26:43 AM	TRK;0043;- 03329.3010;+07036.6786;070813;113051	8/13/2007	15286
0008	TRK	0044		-33.48835	-70.61131	7:26:43 AM	TRK;0044;- 03329.3010;+07036.6786;070813;113257	8/13/2007	15287
0008	TRK	0045		-33.48835	-70.61131	7:26:43 AM	TRK;0045;- 03329.3010;+07036.6786;070813;113504	8/13/2007	15288
1234	EOT			0	0		EOT;1234;000173	8/13/2007 7:26:43 AM	15289
1234	SOT			0	0		SOT;1234	8/13/2007 7:31:42 AM	15290
0008	TRK	0046		-33.48835	-70.61131	7:31:42 AM	TRK;0046;- 03329.3010;+07036.6786;070813;113656	8/13/2007	15291
0008	TRK	0047		-33.48835	-70.61131	7:31:43 AM	TRK;0047;- 03329.3010;+07036.6786;070813;113903	8/13/2007	15292
1234	EOT			0	0		EOT;1234;000125	8/13/2007 7:31:43 AM	15293
1234	SOT			0	0		SOT;1234	8/13/2007 7:36:43 AM	15294
0008	TRK	0048		-33.48835	-70.61131	7:36:44 AM	TRK;0048;- 03329.3010;+07036.6786;070813;114055	8/13/2007	15295
0008	TRK	0049		-33.48835	-70.61131	7:36:44 AM	TRK;0049;- 03329.3010;+07036.6786;070813;114302	8/13/2007	15296
0008	TRK	0050		-33.48835	-70.61131	7:36:44 AM	TRK;0050;- 03329.3010;+07036.6786;070813;114508	8/13/2007	15297
1234	EOT			0	0		EOT;1234;000173	8/13/2007 7:36:44 AM	15298
1234	SOT			0	0		SOT;1234	8/13/2007 7:41:44 AM	15299
0008	TRK	0051		-33.48835	-70.61131	7:41:44 AM	TRK;0051;- 03329.3010;+07036.6786;070813;114701	8/13/2007	15300
0008	TRK	0052		-33.48835	-70.61131	7:41:45 AM	TRK;0052;- 03329.3010;+07036.6786;070813;114853	8/13/2007	15301
1234	EOT			0	0		EOT;1234;000125	8/13/2007 7:41:45 AM	15302
1234	SOT			0	0		SOT;1234	8/13/2007 7:46:43 AM	15303
0008	TRK	0053		-33.48835	-70.61131	7:46:44 AM	TRK;0053;- 03329.3010;+07036.6786;070813;115100	8/13/2007	15304
0008	TRK	0054		-33.48835	-70.61131	7:46:44 AM	TRK;0054;- 03329.3010;+07036.6786;070813;115252	8/13/2007	15305

0008	TRK	0055		-33.48835	-70.61131	7:46:44 AM	TRK;0055;- 03329.3010;+07036.6786;070813;115513	8/13/2007	15306
1234	EOT			0	0		EOT;1234;000173	8/13/2007 7:46:44 AM	15307
1234	SOT			0	0		SOT;1234	8/13/2007 7:51:45 AM	15308
0008	TRK	0056		-33.48835	-70.61131	7:51:45 AM	TRK;0056;- 03329.3010;+07036.6786;070813;115705	8/13/2007	15309
0008	TRK	0057		-33.48835	-70.61131	7:51:45 AM	TRK;0057;- 03329.3010;+07036.6786;070813;115858	8/13/2007	15310
1234	EOT			0	0		EOT;1234;000125	8/13/2007 7:51:45 AM	15311
1234	SOT			0	0		SOT;1234	8/13/2007 7:56:45 AM	15312
0008	TRK	0058		-33.48835	-70.61131	7:56:45 AM	TRK;0058;- 03329.3010;+07036.6786;070813;120104	8/13/2007	15313
0008	TRK	0059		-33.48835	-70.61131	7:56:45 AM	TRK;0059;- 03329.3010;+07036.6786;070813;120257	8/13/2007	15314
0008	TRK	0060		-33.48835	-70.61131	7:56:46 AM	TRK;0060;- 03329.3010;+07036.6786;070813;120517	8/13/2007	15315
1234	EOT			0	0		EOT;1234;000173	8/13/2007 7:56:46 AM	15316
1234	SOT			0	0		SOT;1234	8/13/2007 8:01:46 AM	15317
0008	TRK	0061		-33.48835	-70.61131	8:01:46 AM	TRK;0061;- 03329.3010;+07036.6786;070813;120656	8/13/2007	15318
0008	TRK	0062		-33.48835	-70.61131	8:01:46 AM	TRK;0062;- 03329.3010;+07036.6786;070813;120902	8/13/2007	15319
1234	EOT			0	0		EOT;1234;000125	8/13/2007 8:01:46 AM	15320
1234	SOT			0	0		SOT;1234	8/13/2007 8:06:46 AM	15321
0008	TRK	0063		-33.48835	-70.61131	8:06:47 AM	TRK;0063;- 03329.3010;+07036.6786;070813;121055	8/13/2007	15322
0008	TRK	0064		-33.48835	-70.61131	8:06:47 AM	TRK;0064;- 03329.3010;+07036.6786;070813;121301	8/13/2007	15323
0008	TRK	0065		-33.48835	-70.61131	8:06:47 AM	TRK;0065;- 03329.3010;+07036.6786;070813;121508	8/13/2007	15324
1234	EOT			0	0		EOT;1234;000173	8/13/2007 8:06:47 AM	15325
1234	SOT			0	0		SOT;1234	8/13/2007 8:11:47 AM	15326
0008	TRK	0066		-33.48835	-70.61131	8:11:47 AM	TRK;0066;- 03329.3010;+07036.6786;070813;121700	8/13/2007	15327
0008	TRK	0067		-33.48835	-70.61131	8:11:48 AM	TRK;0067;- 03329.3010;+07036.6786;070813;121907	8/13/2007	15328
1234	EOT			0	0		EOT;1234;000125	8/13/2007 8:11:48 AM	15329
1234	SOT			0	0		SOT;1234	8/13/2007 8:16:47 AM	15330
0008	TRK	0068		-33.48835	-70.61131	8:16:48 AM	TRK;0068;-	8/13/2007	15331

							03329.3010;+07036.6786;070813;122059		
0008	TRK	0069		-33.48835	-70.61131	8:16:48 AM	TRK;0069;- 03329.3010;+07036.6786;070813;122306	8/13/2007	15332
0008	TRK	0070		-33.48835	-70.61131	8:16:48 AM	TRK;0070;- 03329.3010;+07036.6786;070813;122512	8/13/2007	15333
1234	EOT			0	0		EOT;1234;000173	8/13/2007 8:16:48 AM	15334
1234	SOT			0	0		SOT;1234	8/13/2007 8:21:48 AM	15335
0008	TRK	0071		-33.48835	-70.61131	8:21:48 AM	TRK;0071;- 03329.3010;+07036.6786;070813;122705	8/13/2007	15336
0008	TRK	0072		-33.48835	-70.61131	8:21:49 AM	TRK;0072;- 03329.3010;+07036.6786;070813;122857	8/13/2007	15337
1234	EOT			0	0		EOT;1234;000125	8/13/2007 8:21:49 AM	15338
1234	SOT			0	0		SOT;1234	8/13/2007 8:26:48 AM	15339
0008	TRK	0073		-33.48835	-70.61131	8:26:49 AM	TRK;0073;- 03329.3010;+07036.6786;070813;123104	8/13/2007	15340
0008	TRK	0074		-33.48835	-70.61131	8:26:49 AM	TRK;0074;- 03329.3010;+07036.6786;070813;123256	8/13/2007	15341
0008	TRK	0075		-33.48835	-70.61131	8:26:49 AM	TRK;0075;- 03329.3010;+07036.6786;070813;123517	8/13/2007	15342
1234	EOT			0	0		EOT;1234;000173	8/13/2007 8:26:49 AM	15343
1234	SOT			0	0		SOT;1234	8/13/2007 8:31:48 AM	15344
0008	TRK	0076		-33.48835	-70.61131	8:31:49 AM	TRK;0076;- 03329.3010;+07036.6786;070813;123709	8/13/2007	15345
0008	TRK	0077		-33.48835	-70.61131	8:31:49 AM	TRK;0077;- 03329.3010;+07036.6786;070813;123902	8/13/2007	15346
1234	EOT			0	0		EOT;1234;000125	8/13/2007 8:31:49 AM	15347
1234	SOT			0	0		SOT;1234	8/13/2007 8:36:50 AM	15348
0008	TRK	0078		-33.48835	-70.61131	8:36:50 AM	TRK;0078;- 03329.3010;+07036.6786;070813;124108	8/13/2007	15349
0008	TRK	0079		-33.48835	-70.61131	8:36:50 AM	TRK;0079;- 03329.3010;+07036.6786;070813;124301	8/13/2007	15350
0008	TRK	0080		-33.48835	-70.61131	8:36:50 AM	TRK;0080;- 03329.3010;+07036.6786;070813;124521	8/13/2007	15351
1234	EOT			0	0		EOT;1234;000173	8/13/2007 8:36:50 AM	15352
1234	SOT			0	0		SOT;1234	8/13/2007 8:41:50 AM	15353
0008	TRK	0081		-33.48835	-70.61131	8:41:51 AM	TRK;0081;- 03329.3010;+07036.6786;070813;124700	8/13/2007	15354
0008	TRK	0082		-33.48835	-70.61131	8:41:51 AM	TRK;0082;- 03329.3010;+07036.6786;070813;124906	8/13/2007	15355
1234	EOT			0	0		EOT;1234;000125	8/13/2007 8:41:51 AM	15356

1234	SOT			0	0		SOT;1234	8/13/2007 8:46:51 AM	15357
0008	TRK	0083		-33.48835	-70.61131	8:46:52 AM	TRK;0083;- 03329.3010;+07036.6786;070813;125059	8/13/2007	15358
0008	TRK	0084		-33.48835	-70.61131	8:46:52 AM	TRK;0084;- 03329.3010;+07036.6786;070813;125305	8/13/2007	15359
0008	TRK	0085		-33.48835	-70.61131	8:46:52 AM	TRK;0085;- 03329.3010;+07036.6786;070813;125512	8/13/2007	15360
1234	EOT			0	0		EOT;1234;000173	8/13/2007 8:46:52 AM	15361
1234	SOT			0	0		SOT;1234	8/13/2007 8:51:51 AM	15362
0008	TRK	0086		-33.48835	-70.61131	8:51:52 AM	TRK;0086;- 03329.3010;+07036.6786;070813;125704	8/13/2007	15363
0008	TRK	0087		-33.48835	-70.61131	8:51:52 AM	TRK;0087;- 03329.3010;+07036.6786;070813;125911	8/13/2007	15364
1234	EOT			0	0		EOT;1234;000125	8/13/2007 8:51:52 AM	15365
1234	SOT			0	0		SOT;1234	8/13/2007 8:56:52 AM	15366
0008	TRK	0088		-33.48835	-70.61131	8:56:53 AM	TRK;0088;- 03329.3010;+07036.6786;070813;130103	8/13/2007	15367
0008	TRK	0089		-33.48835	-70.61131	8:56:53 AM	TRK;0089;- 03329.3010;+07036.6786;070813;130310	8/13/2007	15368
0008	TRK	0090		-33.48835	-70.61131	8:56:53 AM	TRK;0090;- 03329.3010;+07036.6786;070813;130516	8/13/2007	15369
1234	EOT			0	0		EOT;1234;000173	8/13/2007 8:56:53 AM	15370
1234	SOT			0	0		SOT;1234	8/13/2007 9:01:54 AM	15371
0008	TRK	0091		-33.48835	-70.61131	9:01:54 AM	TRK;0091;- 03329.3010;+07036.6786;070813;130709	8/13/2007	15372
0008	TRK	0092		-33.48835	-70.61131	9:01:54 AM	TRK;0092;- 03329.3010;+07036.6786;070813;130901	8/13/2007	15373
1234	EOT			0	0		EOT;1234;000125	8/13/2007 9:01:55 AM	15374
1234	SOT			0	0		SOT;1234	8/13/2007 9:06:53 AM	15375
0008	TRK	0093		-33.48835	-70.61131	9:06:54 AM	TRK;0093;- 03329.3010;+07036.6786;070813;131108	8/13/2007	15376
0008	TRK	0094		-33.48835	-70.61131	9:06:54 AM	TRK;0094;- 03329.3010;+07036.6786;070813;131314	8/13/2007	15377
0008	TRK	0095		-33.48835	-70.61131	9:06:54 AM	TRK;0095;- 03329.3010;+07036.6786;070813;131521	8/13/2007	15378
1234	EOT			0	0		EOT;1234;000173	8/13/2007 9:06:54 AM	15379
1234	SOT			0	0		SOT;1234	8/13/2007 9:11:54 AM	15380
0008	TRK	0096		-33.48835	-70.61131	9:11:54 AM	TRK;0096;- 03329.3010;+07036.6786;070813;131713	8/13/2007	15381
0008	TRK	0097		-33.48835	-70.61131	9:11:54 AM	TRK;0097;-	8/13/2007	15382

							03329.3010;+07036.6786;070813;131906		
1234	EOT			0	0		EOT;1234;000125	8/13/2007 9:11:54 AM	15383
1234	SOT			0	0		SOT;1234	8/13/2007 9:16:54 AM	15384
0008	TRK	0098		-33.48835	-70.61131	9:16:54 AM	TRK;0098;- 03329.3010;+07036.6786;070813;132112	8/13/2007	15385
0008	TRK	0099		-33.48835	-70.61131	9:16:55 AM	TRK;0099;- 03329.3010;+07036.6786;070813;132305	8/13/2007	15386
0008	TRK	0100		-33.48835	-70.61131	9:16:55 AM	TRK;0100;- 03329.3010;+07036.6786;070813;132525	8/13/2007	15387
1234	EOT			0	0		EOT;1234;000173	8/13/2007 9:16:55 AM	15388
1234	SOT			0	0		SOT;1234	8/13/2007 9:21:54 AM	15389
0008	TRK	0101		-33.48835	-70.61131	9:21:55 AM	TRK;0101;- 03329.3010;+07036.6786;070813;132704	8/13/2007	15390
0008	TRK	0102		-33.48835	-70.61131	9:21:55 AM	TRK;0102;- 03329.3010;+07036.6786;070813;132910	8/13/2007	15391
1234	EOT			0	0		EOT;1234;000125	8/13/2007 9:21:55 AM	15392
1234	SOT			0	0		SOT;1234	8/13/2007 9:26:55 AM	15393
0008	TRK	0103		-33.48835	-70.61131	9:26:56 AM	TRK;0103;- 03329.3010;+07036.6786;070813;133103	8/13/2007	15394
0008	TRK	0104		-33.48835	-70.61131	9:26:56 AM	TRK;0104;- 03329.3010;+07036.6786;070813;133309	8/13/2007	15395
0008	TRK	0105		-33.48835	-70.61131	9:26:56 AM	TRK;0105;- 03329.3010;+07036.6786;070813;133530	8/13/2007	15396
1234	EOT			0	0		EOT;1234;000173	8/13/2007 9:26:56 AM	15397
1234	SOT			0	0		SOT;1234	8/13/2007 9:31:56 AM	15398
0008	TRK	0106		-33.48835	-70.61131	9:31:57 AM	TRK;0106;- 03329.3010;+07036.6786;070813;133708	8/13/2007	15399
0008	TRK	0107		-33.48835	-70.61131	9:31:57 AM	TRK;0107;- 03329.3010;+07036.6786;070813;133915	8/13/2007	15400
1234	EOT			0	0		EOT;1234;000125	8/13/2007 9:31:57 AM	15401
1234	SOT			0	0		SOT;1234	8/13/2007 9:36:57 AM	15402
0008	TRK	0108		-33.48835	-70.61131	9:36:58 AM	TRK;0108;- 03329.3010;+07036.6786;070813;134107	8/13/2007	15403
0008	TRK	0109		-33.48835	-70.61131	9:36:58 AM	TRK;0109;- 03329.3010;+07036.6786;070813;134314	8/13/2007	15404
0008	TRK	0110		-33.48835	-70.61131	9:36:58 AM	TRK;0110;- 03329.3010;+07036.6786;070813;134520	8/13/2007	15405
1234	EOT			0	0		EOT;1234;000173	8/13/2007 9:36:58 AM	15406
1234	SOT			0	0		SOT;1234	8/13/2007 9:41:59 AM	15407

0008	TRK	0111		-33.48835	-70.61131	9:41:59 AM	TRK;0111;- 03329.3010;+07036.6786;070813;134713	8/13/2007	15408
0008	TRK	0112		-33.48835	-70.61131	9:41:59 AM	TRK;0112;- 03329.3010;+07036.6786;070813;134905	8/13/2007	15409
1234	EOT			0	0		EOT;1234;000125	8/13/2007 9:41:59 AM	15410
1234	SOT			0	0		SOT;1234	8/13/2007 9:46:58 AM	15411
0008	TRK	0113		-33.48835	-70.61131	9:46:59 AM	TRK;0113;- 03329.3010;+07036.6786;070813;135112	8/13/2007	15412
0008	TRK	0114		-33.48835	-70.61131	9:46:59 AM	TRK;0114;- 03329.3010;+07036.6786;070813;135318	8/13/2007	15413
0008	TRK	0115		-33.48835	-70.61131	9:46:59 AM	TRK;0115;- 03329.3010;+07036.6786;070813;135525	8/13/2007	15414
1234	EOT			0	0		EOT;1234;000173	8/13/2007 9:46:59 AM	15415
1234	SOT			0	0		SOT;1234	8/13/2007 9:51:59 AM	15416
0008	TRK	0116		-33.48835	-70.61131	9:52:00 AM	TRK;0116;- 03329.3010;+07036.6786;070813;135717	8/13/2007	15417
0008	TRK	0117		-33.48835	-70.61131	9:52:00 AM	TRK;0117;- 03329.3010;+07036.6786;070813;135910	8/13/2007	15418
1234	EOT			0	0		EOT;1234;000125	8/13/2007 9:52:00 AM	15419
1234	SOT			0	0		SOT;1234	8/13/2007 9:56:59 AM	15420
0008	TRK	0118		-33.48835	-70.61131	9:56:59 AM	TRK;0118;- 03329.3010;+07036.6786;070813;140116	8/13/2007	15421
0008	TRK	0119		-33.48835	-70.61131	9:56:59 AM	TRK;0119;- 03329.3010;+07036.6786;070813;140309	8/13/2007	15422
0008	TRK	0120		-33.48835	-70.61131	9:57:00 AM	TRK;0120;- 03329.3010;+07036.6786;070813;140529	8/13/2007	15423
1234	EOT			0	0		EOT;1234;000173	8/13/2007 9:57:00 AM	15424
1234	SOT			0	0		SOT;1234	8/13/2007 10:04:24 AM	15425
0008	DEV	0121	9004101013113	-33.48835	-70.61131	10:04:24 AM	DEV;0121;9004101013113;- 03329.3010;+07036.6786;070813;140708	8/13/2007	15426
0008	DEV	0122	7802600133217	-33.48835	-70.61131	10:04:24 AM	DEV;0122;7802600133217;- 03329.3010;+07036.6786;070813;140708	8/13/2007	15427
0008	DEV	0123	4005808829958	-33.48835	-70.61131	10:04:24 AM	DEV;0123;4005808829958;- 03329.3010;+07036.6786;070813;140708	8/13/2007	15428
0008	TRK	0124		-33.48835	-70.61131	10:04:25 AM	TRK;0124;- 03329.3010;+07036.6786;070813;140804	8/13/2007	15429
0008	DEV	0125	80629845201	-33.48835	-70.61131	10:04:25 AM	DEV;0125;80629845201;- 03329.3010;+07036.6786;070813;140846	8/13/2007	15430
0008	DEV	0126	800437791100	-33.48835	-70.61131	10:04:26 AM	DEV;0126;800437791100;- 03329.3010;+07036.6786;070813;140846	8/13/2007	15431
0008	DEV	0127	F2000290195@@@	-33.48835	-70.61131	10:04:26 AM	DEV;0127;F2000290195@@@;- 03329.3010;+07036.6786;070813;140900	8/13/2007	15432
0008	DEV	0128	7802600133217	-33.48835	-70.61131	10:04:26 AM	DEV;0128;7802600133217;-	8/13/2007	15433

							03329.3010;+07036.6786;070813;141039		
0008	DEV	0129	9004101013113	-33.48835	-70.61131	10:04:26 AM	DEV;0129;9004101013113;- 03329.3010;+07036.6786;070813;141039	8/13/2007	15434
0008	TRK	0130		-33.48835	-70.61131	10:04:26 AM	TRK;0130;- 03329.3010;+07036.6786;070813;141135	8/13/2007	15435
1234	EOT			0	0		EOT;1234;000620	8/13/2007 10:04:30 AM	15436
1234	SOT			0	0		SOT;1234	8/13/2007 10:09:24 AM	15437
0008	TRK	0131		-33.48835	-70.61131	10:09:26 AM	TRK;0131;- 03329.3010;+07036.6786;070813;141341	8/13/2007	15438
0008	TRK	0132		-33.4884733333333	-70.61139	10:09:26 AM	TRK;0132;- 03329.3084;+07036.6834;070813;141530	8/13/2007	15439
0008	TRK	0133		-33.488405	-70.61135	10:09:26 AM	TRK;0133;- 03329.3043;+07036.6810;070813;141745	8/13/2007	15440
1234	EOT			0	0		EOT;1234;000173	8/13/2007 10:09:26 AM	15441
1234	SOT			0	0		SOT;1234	8/13/2007 10:14:25 AM	15442
0008	TRK	0134		-33.4884766666667	-70.6114266666667	10:14:25 AM	TRK;0134;- 03329.3086;+07036.6856;070813;141945	8/13/2007	15443
0008	TRK	0135		-33.4884833333333	-70.6114383333333	10:14:25 AM	TRK;0135;- 03329.3090;+07036.6863;070813;142145	8/13/2007	15444
1234	EOT			0	0		EOT;1234;000125	8/13/2007 10:14:25 AM	15445
1234	SOT			0	0		SOT;1234	8/13/2007 10:20:08 AM	15446
0008	TRK	0136		-33.4884183333333	-70.6114033333333	10:20:09 AM	TRK;0136;- 03329.3051;+07036.6842;070813;142415	8/13/2007	15447
0008	TRK	0137		-33.4884083333333	-70.6113916666667	10:20:09 AM	TRK;0137;- 03329.3045;+07036.6835;070813;142615	8/13/2007	15448
0008	TRK	0138		-33.4879216666667	-70.6118566666667	10:20:09 AM	TRK;0138;- 03329.2753;+07036.7114;070813;142830	8/13/2007	15449
1234	EOT			0	0		EOT;1234;000173	8/13/2007 10:20:10 AM	15450
1234	SOT			0	0		SOT;1234	8/13/2007 10:25:09 AM	15451
0008	TRK	0139		-33.491475	-70.6173416666667	10:25:09 AM	TRK;0139;- 03329.4885;+07037.0405;070813;143015	8/13/2007	15452
0008	TRK	0140		-33.5051583333333	-70.61469	10:25:09 AM	TRK;0140;- 03330.3095;+07036.8814;070813;143215	8/13/2007	15453
1234	EOT			0	0		EOT;1234;000125	8/13/2007 10:25:09 AM	15454
1234	SOT			0	0		SOT;1234	8/13/2007 10:30:08 AM	15455
0008	TRK	0141		-33.5156	-70.61099	10:30:09 AM	TRK;0141;- 03330.9360;+07036.6594;070813;143415	8/13/2007	15456
0008	TRK	0142		-33.528765	-70.6132	10:30:09 AM	TRK;0142;- 03331.7259;+07036.7920;070813;143615	8/13/2007	15457
0008	TRK	0143		-33.53042	-70.630135	10:30:09 AM	TRK;0143;- 03331.8252;+07037.8081;070813;143830	8/13/2007	15458

1234	EOT			0	0		EOT;1234;000173	8/13/2007 10:30:09 AM	15459
1234	SOT			0	0		SOT;1234	8/13/2007 10:37:44 AM	15460
0008	TRK	0144		- 33.5306983333333	- 70.6281666666667	10:37:45 AM	TRK;0144;- 03331.8419;+07037.6900;070813;144133	8/13/2007	15461
0008	TRK	0145		- 33.5306983333333	- 70.6281666666667	10:37:45 AM	TRK;0145;- 03331.8419;+07037.6900;070813;144407	8/13/2007	15462
1234	EOT			0	0		EOT;1234;000125	8/13/2007 10:37:45 AM	15463
1234	SOT			0	0		SOT;1234	8/13/2007 10:42:46 AM	15464
0008	TRK	0146		- 33.5306983333333	- 70.6281666666667	10:42:46 AM	TRK;0146;- 03331.8419;+07037.6900;070813;144752	8/13/2007	15465
0008	TRK	0147		- 33.5306983333333	- 70.6281666666667	10:42:47 AM	TRK;0147;- 03331.8419;+07037.6900;070813;144903	8/13/2007	15466
0008	TRK	0148		- 33.5306983333333	- 70.6281666666667	10:42:47 AM	TRK;0148;- 03331.8419;+07037.6900;070813;145109	8/13/2007	15467
1234	EOT			0	0		EOT;1234;000173	8/13/2007 10:42:47 AM	15468
1234	SOT			0	0		SOT;1234	8/13/2007 10:47:47 AM	15469
0008	TRK	0149		- 33.5306983333333	- 70.6281666666667	10:47:47 AM	TRK;0149;- 03331.8419;+07037.6900;070813;145302	8/13/2007	15470
0008	TRK	0150		- 33.5306983333333	- 70.6281666666667	10:47:47 AM	TRK;0150;- 03331.8419;+07037.6900;070813;145454	8/13/2007	15471
1234	EOT			0	0		EOT;1234;000125	8/13/2007 10:47:47 AM	15472
1234	SOT			0	0		SOT;1234	8/13/2007 10:52:47 AM	15473
0008	TRK	0151		- 33.5306983333333	- 70.6281666666667	10:52:47 AM	TRK;0151;- 03331.8419;+07037.6900;070813;145701	8/13/2007	15474
0008	TRK	0152		- 33.5306983333333	- 70.6281666666667	10:52:47 AM	TRK;0152;- 03331.8419;+07037.6900;070813;145907	8/13/2007	15475
0008	TRK	0153		- 33.5306983333333	- 70.6281666666667	10:52:47 AM	TRK;0153;- 03331.8419;+07037.6900;070813;150114	8/13/2007	15476
1234	EOT			0	0		EOT;1234;000173	8/13/2007 10:52:47 AM	15477
1234	SOT			0	0		SOT;1234	8/13/2007 10:57:47 AM	15478
0008	TRK	0154		- 33.5306983333333	- 70.6281666666667	10:57:48 AM	TRK;0154;- 03331.8419;+07037.6900;070813;150306	8/13/2007	15479
0008	TRK	0155		- 33.5306983333333	- 70.6281666666667	10:57:48 AM	TRK;0155;- 03331.8419;+07037.6900;070813;150459	8/13/2007	15480
1234	EOT			0	0		EOT;1234;000125	8/13/2007 10:57:48 AM	15481
1234	SOT			0	0		SOT;1234	8/13/2007 11:02:49 AM	15482
0008	TRK	0156		- 33.5306983333333	- 70.6281666666667	11:02:49 AM	TRK;0156;- 03331.8419;+07037.6900;070813;150705	8/13/2007	15483
0008	TRK	0157		-	-	11:02:50 AM	TRK;0157;-	8/13/2007	15484

				33.5306983333333	70.6281666666667		03331.8419;+07037.6900;070813;150858		
0008	TRK	0158		- 33.5306983333333	- 70.6281666666667	11:02:50 AM	TRK;0158;- 03331.8419;+07037.6900;070813;151118	8/13/2007	15485
1234	EOT			0	0		EOT;1234;000173	8/13/2007 11:02:50 AM	15486
1234	SOT			0	0		SOT;1234	8/13/2007 11:07:49 AM	15487
0008	TRK	0159		- 33.5306983333333	- 70.6281666666667	11:07:49 AM	TRK;0159;- 03331.8419;+07037.6900;070813;151257	8/13/2007	15488
0008	TRK	0160		- 33.5306983333333	- 70.6281666666667	11:07:49 AM	TRK;0160;- 03331.8419;+07037.6900;070813;151503	8/13/2007	15489
1234	EOT			0	0		EOT;1234;000125	8/13/2007 11:07:49 AM	15490
1234	SOT			0	0		SOT;1234	8/13/2007 11:12:50 AM	15491
0008	TRK	0161		- 33.5306983333333	- 70.6281666666667	11:12:51 AM	TRK;0161;- 03331.8419;+07037.6900;070813;151710	8/13/2007	15492
0008	TRK	0162		- 33.5306983333333	- 70.6281666666667	11:12:51 AM	TRK;0162;- 03331.8419;+07037.6900;070813;151902	8/13/2007	15493
0008	TRK	0163		- 33.5306983333333	- 70.6281666666667	11:12:51 AM	TRK;0163;- 03331.8419;+07037.6900;070813;152123	8/13/2007	15494
1234	EOT			0	0		EOT;1234;000173	8/13/2007 11:12:51 AM	15495
1234	SOT			0	0		SOT;1234	8/13/2007 11:17:51 AM	15496
0008	TRK	0164		- 33.5306983333333	- 70.6281666666667	11:17:51 AM	TRK;0164;- 03331.8419;+07037.6900;070813;152301	8/13/2007	15497
0008	TRK	0165		- 33.5306983333333	- 70.6281666666667	11:17:51 AM	TRK;0165;- 03331.8419;+07037.6900;070813;152508	8/13/2007	15498
1234	EOT			0	0		EOT;1234;000125	8/13/2007 11:17:51 AM	15499
1234	SOT			0	0		SOT;1234	8/13/2007 11:22:51 AM	15500
0008	TRK	0166		- 33.5306983333333	- 70.6281666666667	11:22:52 AM	TRK;0166;- 03331.8419;+07037.6900;070813;152700	8/13/2007	15501
0008	TRK	0167		- 33.5306983333333	- 70.6281666666667	11:22:52 AM	TRK;0167;- 03331.8419;+07037.6900;070813;152907	8/13/2007	15502
0008	TRK	0168		- 33.5306983333333	- 70.6281666666667	11:22:52 AM	TRK;0168;- 03331.8419;+07037.6900;070813;153113	8/13/2007	15503
1234	EOT			0	0		EOT;1234;000173	8/13/2007 11:22:52 AM	15504
1234	SOT			0	0		SOT;1234	8/13/2007 11:27:51 AM	15505
0008	TRK	0169		- 33.5306983333333	- 70.6281666666667	11:27:52 AM	TRK;0169;- 03331.8419;+07037.6900;070813;153306	8/13/2007	15506
0008	TRK	0170		- 33.5306983333333	- 70.6281666666667	11:27:52 AM	TRK;0170;- 03331.8419;+07037.6900;070813;153512	8/13/2007	15507
1234	EOT			0	0		EOT;1234;000125	8/13/2007 11:27:52 AM	15508
1234	SOT			0	0		SOT;1234	8/13/2007 11:32:51 AM	15509

0008	TRK	0171	-	33.53069833333333	70.62816666666667	11:32:52 AM	TRK;0171;- 03331.8419;+07037.6900;070813;153705	8/13/2007	15510
0008	TRK	0172	-	33.53069833333333	70.62816666666667	11:32:52 AM	TRK;0172;- 03331.8419;+07037.6900;070813;153911	8/13/2007	15511
0008	TRK	0173	-	33.53069833333333	70.62816666666667	11:32:52 AM	TRK;0173;- 03331.8419;+07037.6900;070813;154118	8/13/2007	15512
1234	EOT		0		0		EOT;1234;000173	8/13/2007 11:32:52 AM	15513
1234	SOT		0		0		SOT;1234	8/13/2007 11:37:52 AM	15514
0008	TRK	0174	-	33.53069833333333	70.62816666666667	11:37:53 AM	TRK;0174;- 03331.8419;+07037.6900;070813;154310	8/13/2007	15515
0008	TRK	0175	-	33.53069833333333	70.62816666666667	11:37:53 AM	TRK;0175;- 03331.8419;+07037.6900;070813;154503	8/13/2007	15516
1234	EOT		0		0		EOT;1234;000125	8/13/2007 11:37:53 AM	15517
1234	SOT		0		0		SOT;1234	8/13/2007 11:42:53 AM	15518
0008	TRK	0176	-	33.53069833333333	70.62816666666667	11:42:54 AM	TRK;0176;- 03331.8419;+07037.6900;070813;154709	8/13/2007	15519
0008	TRK	0177	-	33.53069833333333	70.62816666666667	11:42:54 AM	TRK;0177;- 03331.8419;+07037.6900;070813;154902	8/13/2007	15520
0008	TRK	0178	-	33.53069833333333	70.62816666666667	11:42:54 AM	TRK;0178;- 03331.8419;+07037.6900;070813;155122	8/13/2007	15521
1234	EOT		0		0		EOT;1234;000173	8/13/2007 11:42:54 AM	15522
1234	SOT		0		0		SOT;1234	8/13/2007 11:47:54 AM	15523
0008	TRK	0179	-	33.53069833333333	70.62816666666667	11:47:55 AM	TRK;0179;- 03331.8419;+07037.6900;070813;155301	8/13/2007	15524
0008	TRK	0180	-	33.53069833333333	70.62816666666667	11:47:55 AM	TRK;0180;- 03331.8419;+07037.6900;070813;155507	8/13/2007	15525
1234	EOT		0		0		EOT;1234;000125	8/13/2007 11:47:55 AM	15526
1234	SOT		0		0		SOT;1234	8/13/2007 11:53:34 AM	15527
0008	TRK	0181	-	33.53069833333333	70.62816666666667	11:53:35 AM	TRK;0181;- 03331.8419;+07037.6900;070813;155714	8/13/2007	15528
0008	TRK	0182	-	33.53069833333333	70.62816666666667	11:53:35 AM	TRK;0182;- 03331.8419;+07037.6900;070813;155934	8/13/2007	15529
0008	TRK	0183	-	33.53069833333333	70.62816666666667	11:53:35 AM	TRK;0183;- 03331.8419;+07037.6900;070813;160155	8/13/2007	15530
1234	EOT		0		0		EOT;1234;000173	8/13/2007 11:53:36 AM	15531
1234	SOT		0		0		SOT;1234	8/13/2007 11:59:21 AM	15532
0008	TRK	0184	-	33.53069833333333	70.62816666666667	11:59:22 AM	TRK;0184;- 03331.8419;+07037.6900;070813;160430	8/13/2007	15533
0008	TRK	0185	-	33.53069833333333	70.62816666666667	11:59:22 AM	TRK;0185;- 03331.8419;+07037.6900;070813;160636	8/13/2007	15534
1234	EOT		0		0		EOT;1234;000125	8/13/2007	15535

								11:59:22 AM	
1234	SOT			0	0		SOT;1234	8/13/2007 1:41:57 PM	15536
0008	TRK	0186		- 33.53069833333333	- 70.62816666666667	1:41:58 PM	TRK;0186;- 03331.8419;+07037.6900;070813;160829	8/13/2007	15537
0008	TRK	0187		- 33.53069833333333	- 70.62816666666667	1:41:58 PM	TRK;0187;- 03331.8419;+07037.6900;070813;161035	8/13/2007	15538
0008	TRK	0188		- 33.53069833333333	- 70.62816666666667	1:41:58 PM	TRK;0188;- 03331.8419;+07037.6900;070813;161242	8/13/2007	15539
0008	TRK	0189		- 33.53779833333333	- 70.61892666666667	1:41:59 PM	TRK;0189;- 03332.2679;+07037.1356;070813;161430	8/13/2007	15540
0008	TRK	0190		- 33.54206333333333	- 70.61045166666667	1:41:59 PM	TRK;0190;- 03332.5238;+07036.6271;070813;161630	8/13/2007	15541
0008	TRK	0191		-33.55048	-70.606545	1:41:59 PM	TRK;0191;- 03333.0288;+07036.3927;070813;161830	8/13/2007	15542
0008	TRK	0192		- 33.55888833333333	- 70.60257166666667	1:42:00 PM	TRK;0192;- 03333.5333;+07036.1543;070813;162030	8/13/2007	15543
0008	TRK	0193		- 33.55937833333333	-70.60301	1:42:00 PM	TRK;0193;- 03333.5627;+07036.1806;070813;162230	8/13/2007	15544
0008	TRK	0194		- 33.55939833333333	- 70.60300666666667	1:42:01 PM	TRK;0194;- 03333.5639;+07036.1804;070813;162430	8/13/2007	15545
0008	TRK	0195		- 33.55939666666667	-70.603025	1:42:01 PM	TRK;0195;- 03333.5638;+07036.1815;070813;162630	8/13/2007	15546
0008	TRK	0196		-33.55934	-70.602415	1:42:02 PM	TRK;0196;- 03333.5604;+07036.1449;070813;162830	8/13/2007	15547
0008	DEV	0197	800437905818	- 33.55814833333333	- 70.60025333333333	1:42:02 PM	DEV;0197;800437905818;- 03333.4889;+07036.0152;070813;163130	8/13/2007	15548
0008	TRK	0198		-33.55816	- 70.59996666666667	1:42:03 PM	TRK;0198;- 03333.4896;+07035.9980;070813;163300	8/13/2007	15549
0008	DEV	0199	271310621730	- 33.55817833333333	- 70.59997166666667	1:42:03 PM	DEV;0199;271310621730;- 03333.4907;+07035.9983;070813;163345	8/13/2007	15550
0008	DEV	0200	80627259038	- 33.55797333333333	-70.599975	1:42:03 PM	DEV;0200;80627259038;- 03333.4784;+07035.9985;070813;163500	8/13/2007	15551
0008	DEV	0201	B200352778911	-33.55785	- 70.60006666666667	1:42:03 PM	DEV;0201;B200352778911;- 03333.4710;+07036.0040;070813;163630	8/13/2007	15552
0008	DEV	0202	800437877409	- 33.55782333333333	- 70.59996333333333	1:42:05 PM	DEV;0202;800437877409;- 03333.4694;+07035.9978;070813;163700	8/13/2007	15553
0008	DEV	0203	800437894590	- 33.55769166666667	- 70.59997666666667	1:42:05 PM	DEV;0203;800437894590;- 03333.4615;+07035.9986;070813;163800	8/13/2007	15554
0008	DEV	0204	800437894590	- 33.55771666666667	-70.600025	1:42:05 PM	DEV;0204;800437894590;- 03333.4630;+07036.0015;070813;163845	8/13/2007	15555
0008	DEV	0205	800436955006	-33.557605	- 70.60009833333333	1:42:05 PM	DEV;0205;800436955006;- 03333.4563;+07036.0059;070813;163945	8/13/2007	15556
0008	TRK	0206		- 33.55745166666667	- 70.60004666666667	1:42:06 PM	TRK;0206;- 03333.4471;+07036.0028;070813;164115	8/13/2007	15557
0008	DEV	0207	B200382189720	- 33.55743166666667	- 70.60006333333333	1:42:06 PM	DEV;0207;B200382189720;- 03333.4459;+07036.0038;070813;164230	8/13/2007	15558
0008	DEV	0208	80626285671	-33.55743	- 70.60006333333333	1:42:06 PM	DEV;0208;80626285671;- 03333.4458;+07036.0038;070813;164245	8/13/2007	15559
0008	DEV	0209	800437887721	-33.55742	- 70.60006333333333	1:42:06 PM	DEV;0209;800437887721;- 03333.4452;+07036.0038;070813;164345	8/13/2007	15560

0008	DEV	0210	B200354289511	- 33.55715833333333	- 70.60014666666667	1:42:08 PM	DEV;0210;B200354289511;- 03333.4295;+07036.0088;070813;164445	8/13/2007	15561
0008	DEV	0211	800437886379	-33.55693	- 70.59992666666667	1:42:08 PM	DEV;0211;800437886379;- 03333.4158;+07035.9956;070813;164530	8/13/2007	15562
0008	DEV	0212	800437886379	- 33.55689333333333	- 70.59992333333333	1:42:08 PM	DEV;0212;800437886379;- 03333.4136;+07035.9954;070813;164615	8/13/2007	15563
0008	DEV	0213	80626524307	-33.556905	-70.600255	1:42:08 PM	DEV;0213;80626524307;- 03333.4143;+07036.0153;070813;164745	8/13/2007	15564
0008	DEV	0214	800436871671	- 33.55691333333333	- 70.60028333333333	1:42:08 PM	DEV;0214;800436871671;- 03333.4148;+07036.0170;070813;164800	8/13/2007	15565
0008	TRK	0215		- 33.55738166666667	-70.600355	1:42:08 PM	TRK;0215;- 03333.4429;+07036.0213;070813;164945	8/13/2007	15566
0008	DEV	0216	80626309295	- 33.55710666666667	- 70.60059333333333	1:42:08 PM	DEV;0216;80626309295;- 03333.4264;+07036.0356;070813;165345	8/13/2007	15567
0008	DEV	0217	80627394350	- 33.55708833333333	- 70.60054833333333	1:42:08 PM	DEV;0217;80627394350;- 03333.4253;+07036.0329;070813;165445	8/13/2007	15568
0008	DEV	0218	80626309295	- 33.55707666666667	- 70.60053833333333	1:42:10 PM	DEV;0218;80626309295;- 03333.4246;+07036.0323;070813;165515	8/13/2007	15569
0008	DEV	0219	800437887541	- 33.55704833333333	-70.600535	1:42:10 PM	DEV;0219;800437887541;- 03333.4229;+07036.0321;070813;165545	8/13/2007	15570
0008	TRK	0220		-33.556385	- 70.60070333333333	1:42:10 PM	TRK;0220;- 03333.3831;+07036.0422;070813;165845	8/13/2007	15571
0008	DEV	0221	800437904131	-33.555495	- 70.60042833333333	1:42:11 PM	DEV;0221;800437904131;- 03333.3297;+07036.0257;070813;170130	8/13/2007	15572
0008	TRK	0222		-33.555455	- 70.60042666666667	1:42:11 PM	TRK;0222;- 03333.3273;+07036.0256;070813;170330	8/13/2007	15573
0008	DEV	0223	800436942861	-33.555785	- 70.60037833333333	1:42:11 PM	DEV;0223;800436942861;- 03333.3471;+07036.0227;070813;170400	8/13/2007	15574
0008	DEV	0224	80626691041	- 33.55594333333333	-70.60039	1:42:11 PM	DEV;0224;80626691041;- 03333.3566;+07036.0234;070813;170500	8/13/2007	15575
0008	DEV	0225	800437895308	- 33.55600666666667	- 70.60035666666667	1:42:12 PM	DEV;0225;800437895308;- 03333.3604;+07036.0214;070813;170545	8/13/2007	15576
0008	DEV	0226	800436944638	-33.556045	- 70.60027833333333	1:42:12 PM	DEV;0226;800436944638;- 03333.3627;+07036.0167;070813;170630	8/13/2007	15577
0008	DEV	0227	800436944638	- 33.55607333333333	-70.600285	1:42:12 PM	DEV;0227;800436944638;- 03333.3644;+07036.0171;070813;170700	8/13/2007	15578
0008	DEV	0228	800437608710	- 33.55621333333333	-70.60028	1:42:12 PM	DEV;0228;800437608710;- 03333.3728;+07036.0168;070813;170800	8/13/2007	15579
0008	DEV	0229	80625678572	- 33.55623833333333	-70.60026	1:42:12 PM	DEV;0229;80625678572;- 03333.3743;+07036.0156;070813;170815	8/13/2007	15580
0008	DEV	0230	800437838540	- 33.55625833333333	- 70.60024333333333	1:42:12 PM	DEV;0230;800437838540;- 03333.3755;+07036.0146;070813;170830	8/13/2007	15581
0008	TRK	0231		- 33.55645666666667	-70.600325	1:42:12 PM	TRK;0231;- 03333.3874;+07036.0195;070813;171030	8/13/2007	15582
0008	DEV	0232	B200382372320	-33.55646	-70.600325	1:42:12 PM	DEV;0232;B200382372320;- 03333.3876;+07036.0195;070813;171130	8/13/2007	15583
0008	DEV	0233	800437888954	-33.55646	-70.600325	1:42:13 PM	DEV;0233;800437888954;- 03333.3876;+07036.0195;070813;171200	8/13/2007	15584
0008	TRK	0234		-33.556445	-70.60033	1:42:13 PM	TRK;0234;- 03333.3867;+07036.0198;070813;171400	8/13/2007	15585
0008	DEV	0235	800436907621	-	-	1:42:13 PM	DEV;0235;800436907621;-	8/13/2007	15586

				33.5564166666667	70.6004266666667		03333.3850;+07036.0256;070813;171445		
0008	DEV	0236	800437778544	- 33.5564483333333	- 70.6004966666667	1:42:13 PM	DEV;0236;800437778544;- 03333.3869;+07036.0298;070813;171530	8/13/2007	15587
0008	DEV	0237	800437885110	- 33.5564566666667	- 70.6005083333333	1:42:13 PM	DEV;0237;800437885110;- 03333.3874;+07036.0305;070813;171600	8/13/2007	15588
0008	DEV	0238	800436845308	- 33.5564383333333	- 70.6003483333333	1:42:13 PM	DEV;0238;800436845308;- 03333.3863;+07036.0209;070813;171630	8/13/2007	15589
0008	TRK	0239		- 33.5563966666667	- 70.5997966666667	1:42:13 PM	TRK;0239;- 03333.3838;+07035.9878;070813;171830	8/13/2007	15590
0008	TRK	0240		- 33.5563783333333	-70.59988	1:42:13 PM	TRK;0240;- 03333.3827;+07035.9928;070813;172030	8/13/2007	15591
0008	DEV	0241	800437031923	- 33.5565383333333	- 70.5998266666667	1:42:13 PM	DEV;0241;800437031923;- 03333.3923;+07035.9896;07081	8/13/2007	15592
0008	TRK	0242		-33.556515	- 70.5998183333333	1:42:14 PM	TRK;0242;- 03333.3909;+07035.9891;070813;172315	8/13/2007	15593
0008	DEV	0243	800437401685	- 33.5564833333333	- 70.5998033333333	1:42:14 PM	DEV;0243;800437401685;- 03333.3890;+07035.9882;070813;172515	8/13/2007	15594
0008	DEV	0244	B200381407620	-33.556445	- 70.5997616666667	1:42:14 PM	DEV;0244;B200381407620;- 03333.3867;+07035.9857;070813;172600	8/13/2007	15595
0008	DEV	0245	800436942935	- 33.5564866666667	-70.599675	1:42:14 PM	DEV;0245;800436942935;- 03333.3892;+07035.9805;070813;172615	8/13/2007	15596
0008	DEV	0246	00233526259457	-33.556705	- 70.5996716666667	1:42:14 PM	DEV;0246;00233526259457;- 03333.4023;+07035.9803;070813;172700	8/13/2007	15597
0008	DEV	0247	80627491526	- 33.5566933333333	- 70.5996333333333	1:42:14 PM	DEV;0247;80627491526;- 03333.4016;+07035.9780;070813;172915	8/13/2007	15598
0008	DEV	0248	00232919439453	-33.55669	-70.59963	1:42:14 PM	DEV;0248;00232919439453;- 03333.4014;+07035.9778;070813;172930	8/13/2007	15599
0008	DEV	0249	80628354182	-33.55669	-70.59963	1:42:14 PM	DEV;0249;80628354182;- 03333.4014;+07035.9778;070813;172930	8/13/2007	15600
0008	TRK	0250		0	0	1:42:14 PM	TRK;0250;-03	8/13/2007	15601
0008	DEV	0251	80626408196	- 33.5566283333333	-70.59968	1:42:14 PM	DEV;0251;80626408196;- 03333.3977;+07035.9808;070813;173100	8/13/2007	15602
0008	DEV	0252	B2003545297@@@	- 33.5567483333333	- 70.5997033333333	1:42:14 PM	DEV;0252;B2003545297@@@;- 03333.4049;+07035.9822;070813;173200	8/13/2007	15603
0008	DEV	0253	800437771253	- 33.5570116666667	- 70.5997366666667	1:42:14 PM	DEV;0253;800437771253;- 03333.4207;+07035.9842;070813;173315	8/13/2007	15604
0008	DEV	0254	271321776030	- 33.5570083333333	-70.599745	1:42:14 PM	DEV;0254;271321776030;- 03333.4205;+07035.9847;070813;173330	8/13/2007	15605
0008	DEV	0255	800436961740	- 33.5570416666667	- 70.5997366666667	1:42:14 PM	DEV;0255;800436961740;- 03333.4225;+07035.9842;070813;173345	8/13/2007	15606
0008	DEV	0256	800437843875	- 33.5571483333333	-70.59958	1:42:14 PM	DEV;0256;800437843875;- 03333.4289;+07035.9748;070813;173415	8/13/2007	15607
0008	DEV	0257	800437066999	-33.557355	- 70.5991266666667	1:42:14 PM	DEV;0257;800437066999;- 03333.4413;+07035.9476;070813;173500	8/13/2007	15608
0008	DEV	0258	800436847296	-33.55756	0	1:42:14 PM	DEV;0258;800436847296;-03333.4536;+	8/13/2007	15609
0008	TRK	0261		-33.553685	-70.592635	1:42:18 PM	TRK;0261;- 03333.2211;+07035.5581;070813;174115	8/13/2007	15610
0008	TRK	0262		- 33.5509433333333	- 70.5870966666667	1:42:18 PM	TRK;0262;- 03333.0566;+07035.2258;070813;174315	8/13/2007	15611

0008	TRK	0263	-	33.5352566666667	-70.59295	1:42:18 PM	TRK;0263;- 03332.1154;+07035.5770;070813;174515	8/13/2007	15612
0008	TRK	0264	-	33.5230016666667	70.5981683333333	1:42:18 PM	TRK;0264;- 03331.3801;+07035.8901;070813;174715	8/13/2007	15613
0008	TRK	0265	-	33.5144683333333	-70.604565	1:42:18 PM	TRK;0265;- 03330.8681;+07036.2739;070813;174915	8/13/2007	15614
1234	EOT		0	0			EOT;1234;004533	8/13/2007 1:42:18 PM	15615
1234	SOT		0	0			SOT;1234	8/13/2007 1:47:00 PM	15616
0008	TRK	0266	-	33.5024466666667	70.6151316666667	1:47:01 PM	TRK;0266;- 03330.1468;+07036.9079;070813;175130	8/13/2007	15617
0008	TRK	0267	-	33.4917533333333	-70.61728	1:47:01 PM	TRK;0267;- 03329.5052;+07037.0368;070813;175315	8/13/2007	15618
0008	TRK	0268	-	33.4883383333333	-70.611345	1:47:01 PM	TRK;0268;- 03329.3003;+07036.6807;070813;175530	8/13/2007	15619
1234	EOT		0	0			EOT;1234;000173	8/13/2007 1:47:01 PM	15620
1234	SOT		0	0			SOT;1234	8/13/2007 1:52:08 PM	15621
0008	TRK	0269	-	33.488285	70.6113583333333	1:52:08 PM	TRK;0269;- 03329.2971;+07036.6815;070813;175726	8/13/2007	15622
0008	TRK	0270	-	33.488285	70.6113583333333	1:52:09 PM	TRK;0270;- 03329.2971;+07036.6815;070813;175919	8/13/2007	15623
1234	EOT		0	0			EOT;1234;000125	8/13/2007 1:52:09 PM	15624
1234	SOT		0	0			SOT;1234	8/13/2007 1:57:48 PM	15625
0008	TRK	0271	-	33.488285	70.6113583333333	1:57:49 PM	TRK;0271;- 03329.2971;+07036.6815;070813;180125	8/13/2007	15626
0008	TRK	0272	-	33.488285	70.6113583333333	1:57:49 PM	TRK;0272;- 03329.2971;+07036.6815;070813;180318	8/13/2007	15627
0008	TRK	0273	-	33.488285	70.6113583333333	1:57:49 PM	TRK;0273;- 03329.2971;+07036.6815;070813;180620	8/13/2007	15628
1234	EOT		0	0			EOT;1234;000173	8/13/2007 1:57:49 PM	15629
1234	SOT		0	0			SOT;1234	8/13/2007 2:03:33 PM	15630
0008	TRK	0274	-	33.488285	70.6113583333333	2:03:33 PM	TRK;0274;- 03329.2971;+07036.6815;070813;180759	8/13/2007	15631
0008	TRK	0275	-	33.488285	70.6113583333333	2:03:33 PM	TRK;0275;- 03329.2971;+07036.6815;070813;181005	8/13/2007	15632
1234	EOT		0	0			EOT;1234;000125	8/13/2007 2:03:33 PM	15633
1234	SOT		0	0			SOT;1234	8/13/2007 2:08:31 PM	15634
0008	TRK	0276	-	33.488285	70.6113583333333	2:08:32 PM	TRK;0276;- 03329.2971;+07036.6815;070813;181240	8/13/2007	15635
0008	TRK	0277	-	33.488285	70.6113583333333	2:08:32 PM	TRK;0277;- 03329.2971;+07036.6815;070813;181446	8/13/2007	15636
0008	TRK	0278	-	33.488285	-	2:08:32 PM	TRK;0278;-	8/13/2007	15637

					70.6113583333333		03329.2971;+07036.6815;070813;181653		
1234	EOT			0	0		EOT;1234;000173	8/13/2007 2:08:32 PM	15638
1234	SOT			0	0		SOT;1234	8/13/2007 2:13:31 PM	15639
0008	TRK	0279		-33.488285	- 70.6113583333333	2:13:31 PM	TRK;0279;- 03329.2971;+07036.6815;070813;181845	8/13/2007	15640
0008	TRK	0280		-33.488285	- 70.6113583333333	2:13:31 PM	TRK;0280;- 03329.2971;+07036.6815;070813;182038	8/13/2007	15641
1234	EOT			0	0		EOT;1234;000125	8/13/2007 2:13:32 PM	15642
1234	SOT			0	0		SOT;1234	8/13/2007 2:18:46 PM	15643
0008	TRK	0281		-33.488285	- 70.6113583333333	2:18:47 PM	TRK;0281;- 03329.2971;+07036.6815;070813;182244	8/13/2007	15644
0008	TRK	0282		-33.488285	- 70.6113583333333	2:18:47 PM	TRK;0282;- 03329.2971;+07036.6815;070813;182451	8/13/2007	15645
0008	TRK	0283		-33.488285	- 70.6113583333333	2:18:47 PM	TRK;0283;- 03329.2971;+07036.6815;070813;182657	8/13/2007	15646
1234	EOT			0	0		EOT;1234;000173	8/13/2007 2:18:47 PM	15647
1234	SOT			0	0		SOT;1234	8/13/2007 2:23:34 PM	15648
0008	TRK	0284		-33.488285	- 70.6113583333333	2:23:35 PM	TRK;0284;- 03329.2971;+07036.6815;070813;182850	8/13/2007	15649
0008	TRK	0285		- 33.4882766666667	-70.611175	2:23:35 PM	TRK;0285;- 03329.2966;+07036.6705;070813;183045	8/13/2007	15650
1234	EOT			0	0		EOT;1234;000125	8/13/2007 2:23:35 PM	15651
1234	SOT			0	0		SOT;1234	8/13/2007 2:28:32 PM	15652
0008	TRK	0286		-33.488175	-70.611215	2:28:33 PM	TRK;0286;- 03329.2905;+07036.6729;070813;183245	8/13/2007	15653
0008	TRK	0287		- 33.4882833333333	- 70.6112283333333	2:28:33 PM	TRK;0287;- 03329.2970;+07036.6737;070813;183445	8/13/2007	15654
0008	TRK	0288		-33.48833	-70.61121	2:28:33 PM	TRK;0288;- 03329.2998;+07036.6726;070813;183700	8/13/2007	15655
1234	EOT			0	0		EOT;1234;000173	8/13/2007 2:28:33 PM	15656
1234	SOT			0	0		SOT;1234	8/13/2007 2:33:33 PM	15657
0008	TRK	0289		- 33.4883633333333	-70.611215	2:33:34 PM	TRK;0289;- 03329.3018;+07036.6729;070813;183845	8/13/2007	15658
0008	TRK	0290		-33.48837	-70.611165	2:33:34 PM	TRK;0290;- 03329.3022;+07036.6699;070813;184045	8/13/2007	15659
1234	EOT			0	0		EOT;1234;000125	8/13/2007 2:33:34 PM	15660
1234	SOT			0	0		SOT;1234	8/13/2007 2:38:33 PM	15661
0008	TRK	0291		- 33.4883383333333	- 70.6111883333333	2:38:33 PM	TRK;0291;- 03329.3003;+07036.6713;070813;184245	8/13/2007	15662

0008	TRK	0292	- 33.48841333333333	- 70.61125666666667	2:38:34 PM	TRK;0292;- 03329.3048;+07036.6754;070813;184445	8/13/2007	15663
0008	TRK	0293	- 33.48837833333333	- 70.61124666666667	2:38:34 PM	TRK;0293;- 03329.3027;+07036.6748;070813;184700	8/13/2007	15664
1234	EOT		0	0		EOT;1234;000173	8/13/2007 2:38:34 PM	15665
1234	SOT		0	0		SOT;1234	8/13/2007 2:43:35 PM	15666
0008	TRK	0294	-33.48836	-70.611235	2:43:35 PM	TRK;0294;- 03329.3016;+07036.6741;070813;184845	8/13/2007	15667
0008	TRK	0295	- 33.48833333333333	- 70.61125666666667	2:43:35 PM	TRK;0295;- 03329.3000;+07036.6754;070813;185045	8/13/2007	15668
1234	EOT		0	0		EOT;1234;000125	8/13/2007 2:43:36 PM	15669
1234	SOT		0	0		SOT;1234	8/13/2007 2:48:35 PM	15670
0008	TRK	0296	-33.488385	- 70.61145833333333	2:48:36 PM	TRK;0296;- 03329.3031;+07036.6875;070813;185244	8/13/2007	15671
0008	TRK	0297	- 33.48843833333333	- 70.61134833333333	2:48:36 PM	TRK;0297;- 03329.3063;+07036.6809;070813;185445	8/13/2007	15672
0008	TRK	0298	- 33.48841666666667	-70.611135	2:48:36 PM	TRK;0298;- 03329.3050;+07036.6810;070813;185645	8/13/2007	15673
1234	EOT		0	0		EOT;1234;000173	8/13/2007 2:48:36 PM	15674
1234	SOT		0	0		SOT;1234	8/13/2007 2:53:37 PM	15675
0008	TRK	0299	- 33.48822333333333	-70.611245	2:53:37 PM	TRK;0299;- 03329.2934;+07036.6747;070813;185844	8/13/2007	15676
0008	TRK	0300	- 33.48822333333333	-70.611245	2:53:38 PM	TRK;0300;- 03329.2934;+07036.6747;070813;190050	8/13/2007	15677
1234	EOT		0	0		EOT;1234;000125	8/13/2007 2:53:38 PM	15678
1234	SOT		0	0		SOT;1234	8/13/2007 2:59:11 PM	15679
0008	TRK	0301	- 33.48848833333333	- 70.61122666666667	2:59:11 PM	TRK;0301;- 03329.3093;+07036.6736;070813;190300	8/13/2007	15680
0008	TRK	0302	- 33.48831666666667	-70.611275	2:59:11 PM	TRK;0302;- 03329.2990;+07036.6765;070813;190500	8/13/2007	15681
0008	TRK	0303	- 33.48805333333333	-70.611185	2:59:11 PM	TRK;0303;- 03329.2832;+07036.6711;070813;190745	8/13/2007	15682
1234	EOT		0	0		EOT;1234;000173	8/13/2007 2:59:11 PM	15683
1234	SOT		0	0		SOT;1234	8/13/2007 3:04:09 PM	15684
0008	TRK	0304	- 33.48829666666667	-70.611125	3:04:10 PM	TRK;0304;- 03329.2978;+07036.6750;070813;190930	8/13/2007	15685
0008	TRK	0305	- 33.48837666666667	- 70.61127833333333	3:04:10 PM	TRK;0305;- 03329.3026;+07036.6767;070813;191130	8/13/2007	15686
1234	EOT		0	0		EOT;1234;000125	8/13/2007 3:04:10 PM	15687
1234	SOT		0	0		SOT;1234	8/13/2007	15688

								3:09:12 PM	
0008	TRK	0306	-33.48538	-	70.6125933333333	3:09:13 PM	TRK;0306;- 03329.1228;+07036.7556;070813;191330	8/13/2007	15689
0008	TRK	0307	-	-	-70.61158	3:09:13 PM	TRK;0307;- 03328.4623;+07036.6948;070813;191530	8/13/2007	15690
0008	TRK	0308	-33.4742	-	-70.60651	3:09:13 PM	TRK;0308;- 03328.4520;+07036.3906;070813;191745	8/13/2007	15691
1234	EOT		0		0		EOT;1234;000173	8/13/2007 3:09:13 PM	15692
1234	SOT		0		0		SOT;1234	8/13/2007 3:14:11 PM	15693
0008	TRK	0309	-33.474115	-	70.6063633333333	3:14:11 PM	TRK;0309;- 03328.4469;+07036.3818;070813;191930	8/13/2007	15694
0008	TRK	0310	-	-	-	3:14:11 PM	TRK;0310;- 03328.4239;+07035.7014;070813;192130	8/13/2007	15695
1234	EOT		0		0		EOT;1234;000125	8/13/2007 3:14:11 PM	15696
1234	SOT		0		0		SOT;1234	8/13/2007 3:19:11 PM	15697
0008	TRK	0311	-33.472865	-	-70.582795	3:19:12 PM	TRK;0311;- 03328.3719;+07034.9677;070813;192330	8/13/2007	15698
0008	TRK	0312	-	-	-	3:19:12 PM	TRK;0312;- 03328.2044;+07034.6381;070813;192530	8/13/2007	15699
0008	TRK	0313	-33.471865	-	-70.5633	3:19:12 PM	TRK;0313;- 03328.3119;+07033.7980;070813;192745	8/13/2007	15700
1234	EOT		0		0		EOT;1234;000173	8/13/2007 3:19:12 PM	15701
1234	SOT		0		0		SOT;1234	8/13/2007 3:24:12 PM	15702
0008	TRK	0314	-33.47315	-	-70.55668	3:24:13 PM	TRK;0314;- 03328.3890;+07033.4008;070813;192930	8/13/2007	15703
0008	TRK	0315	-33.46976	-	-70.552525	3:24:13 PM	TRK;0315;- 03328.1856;+07033.1515;070813;193130	8/13/2007	15704
1234	EOT		0		0		EOT;1234;000125	8/13/2007 3:24:13 PM	15705
1234	SOT		0		0		SOT;1234	8/13/2007 3:29:15 PM	15706
0008	TRK	0316	-	-	-	3:29:16 PM	TRK;0316;- 03327.7603;+07033.0752;070813;193345	8/13/2007	15707
0008	TRK	0317	-	-	-70.545775	3:29:16 PM	TRK;0317;- 03327.5030;+07032.7465;070813;193530	8/13/2007	15708
0008	TRK	0318	-	-	-70.54353	3:29:16 PM	TRK;0318;- 03327.0743;+07032.6118;070813;193745	8/13/2007	15709
1234	EOT		0		0		EOT;1234;000173	8/13/2007 3:29:16 PM	15710
1234	SOT		0		0		SOT;1234	8/13/2007 3:34:30 PM	15711
0008	TRK	0319	-	-	-70.543355	3:34:31 PM	TRK;0319;- 03326.5765;+07032.6013;070813;193930	8/13/2007	15712
0008	TRK	0320	-33.433665	-	-	3:34:31 PM	TRK;0320;- 03326.0199;+07032.4761;070813;194130	8/13/2007	15713

1234	EOT			0	0		EOT;1234;000125	8/13/2007 3:34:31 PM	15714
1234	SOT			0	0		SOT;1234	8/13/2007 3:40:40 PM	15715
0008	TRK	0321		-33.4239	- 70.5380266666667	3:40:40 PM	TRK;0321;- 03325.4340;+07032.2816;070813;194345	8/13/2007	15716
0008	TRK	0322		- 33.4162816666667	- 70.5388683333333	3:40:40 PM	TRK;0322;- 03324.9769;+07032.3321;070813;194530	8/13/2007	15717
0008	DEV	0323	0708066152902100378736	- 33.4084833333333	- 70.5400016666667	3:40:40 PM	DEV;0323;0708066152902100378736;- 03324.5090;+07032.4001;070813;194745	8/13/2007	15718
0008	TRK	0324		- 33.4084816666667	- 70.5399416666667	3:40:41 PM	TRK;0324;- 03324.5089;+07032.3965;070813;194900	8/13/2007	15719
1234	EOT			0	0		EOT;1234;000244	8/13/2007 3:40:41 PM	15720
1234	SOT			0	0		SOT;1234	8/13/2007 3:46:40 PM	15721
0008	TRK	0325		-33.40601	-70.53333	3:46:40 PM	TRK;0325;- 03324.3606;+07031.9998;070813;195045	8/13/2007	15722
0008	TRK	0326		- 33.4066416666667	-70.526345	3:46:41 PM	TRK;0326;- 03324.3985;+07031.5807;070813;195245	8/13/2007	15723
0008	DEV	0327	0708066152902100348531	- 33.4074566666667	-70.52587	3:46:41 PM	DEV;0327;0708066152902100348531;- 03324.4474;+07031.5522;070813;195345	8/13/2007	15724
1234	EOT			0	0		EOT;1234;000196	8/13/2007 3:46:41 PM	15725
1234	SOT			0	0		SOT;1234	8/13/2007 3:59:07 PM	15726
0008	TRK	0328		- 33.4057283333333	- 70.5243416666667	3:59:07 PM	TRK;0328;- 03324.3437;+07031.4605;070813;195600	8/13/2007	15727
0008	DEV	0329	0708066152902100407048	- 33.4054916666667	-70.52311	3:59:07 PM	DEV;0329;0708066152902100407048;- 03324.3295;+07031.3866;070813;195800	8/13/2007	15728
0008	DEV	0330	7802600133217	-33.40551	- 70.5231016666667	3:59:08 PM	DEV;0330;7802600133217;- 03324.3306;+07031.3861;070813;195815	8/13/2007	15729
0008	DEV	0331	831109807922	-33.405525	-70.52309	3:59:08 PM	DEV;0331;831109807922;- 03324.3315;+07031.3854;070813;195830	8/13/2007	15730
0008	TRK	0332		- 33.4055516666667	- 70.5230666666667	3:59:09 PM	TRK;0332;- 03324.3331;+07031.3840;070813;195930	8/13/2007	15731
0008	TRK	0333		-33.40557	- 70.5230666666667	3:59:09 PM	TRK;0333;- 03324.3342;+07031.3840;070813;200145	8/13/2007	15732
0008	TRK	0334		-33.40977	-70.521455	3:59:09 PM	TRK;0334;- 03324.5862;+07031.2873;070813;200345	8/13/2007	15733
0008	DEV	0335	B200385529621	-33.40977	-70.521455	3:59:09 PM	DEV;0335;B200385529621;- 03324.5862;+07031.2873;070813;200345	8/13/2007	15734
0008	TRK	0336		- 33.4108183333333	-70.521525	3:59:14 PM	TRK;0336;- 03324.6491;+07031.2915;070813;200545	8/13/2007	15735
0008	DEV	0337	000035425780	- 33.4101466666667	-70.521625	3:59:14 PM	DEV;0337;000035425780;- 03324.6088;+07031.2975;070813;200615	8/13/2007	15736
1234	EOT			0	0		EOT;1234;000586	8/13/2007 3:59:14 PM	15737
1234	SOT			0	0		SOT;1234	8/13/2007 4:08:47 PM	15738
0008	DEV	0338	707110032164	-	-	4:08:47 PM	DEV;0338;707110032164;-	8/13/2007	15739

				33.4104733333333	70.5212133333333		03324.6284;+07031.2728;070813;200815		
0008	DEV	0339	800438915327	-33.4104683333333	-70.5212	4:08:48 PM	DEV;0339;800438915327;-03324.6281;+07031.2720;070813;200845	8/13/2007	15740
0008	TRK	0340		-33.4104633333333	-70.52127	4:08:48 PM	TRK;0340;-03324.6278;+07031.2762;070813;200945	8/13/2007	15741
0008	DEV	0341	B200391620625	-33.410515	-70.5211783333333	4:08:48 PM	DEV;0341;B200391620625;-03324.6309;+07031.2707;070813;201130	8/13/2007	15742
0008	DEV	0342	692006122504	-33.410515	-70.5211783333333	4:08:49 PM	DEV;0342;692006122504;-03324.6309;+07031.2707;070813;201130	8/13/2007	15743
0008	TRK	0343		-33.41044	-70.5212166666667	4:08:49 PM	TRK;0343;-03324.6264;+07031.2730;070813;201230	8/13/2007	15744
0008	DEV	0344	B200385174221	-33.40988	-70.52141	4:08:49 PM	DEV;0344;B200385174221;-03324.5928;+07031.2846;070813;201400	8/13/2007	15745
0008	DEV	0345	7802600133217	-33.4098766666667	-70.5214016666667	4:08:49 PM	DEV;0345;7802600133217;-03324.5926;+07031.2841;070813;201415	8/13/2007	15746
0008	DEV	0346	B200385174221	-33.4098766666667	-70.5214016666667	4:08:50 PM	DEV;0346;B200385174221;-03324.5926;+07031.2841;070813;201415	8/13/2007	15747
0008	DEV	0347	B200385174221	-33.4103433333333	-70.521365	4:08:50 PM	DEV;0347;B200385174221;-03324.6206;+07031.2819;070813;201600	8/13/2007	15748
0008	TRK	0348		-33.4096316666667	-70.5212683333333	4:08:50 PM	TRK;0348;-03324.5779;+07031.2761;070813;201715	8/13/2007	15749
1234	EOT			0	0		EOT;1234;000666	8/13/2007 4:08:50 PM	15750
1234	SOT			0	0		SOT;1234	8/13/2007 4:16:15 PM	15751
0008	TRK	0349		-33.4030683333333	-70.5236166666667	4:16:16 PM	TRK;0349;-03324.1841;+07031.4170;070813;201900	8/13/2007	15752
0008	TRK	0350		-33.4028516666667	-70.5159533333333	4:16:16 PM	TRK;0350;-03324.1711;+07030.9572;070813;202100	8/13/2007	15753
0008	DEV	0351	692006234244	-33.40284	-70.5159216666667	4:16:16 PM	DEV;0351;692006234244;-03324.1704;+07030.9553;070813;202200	8/13/2007	15754
0008	DEV	0352	707110008697	-33.40284	-70.5159216666667	4:16:17 PM	DEV;0352;707110008697;-03324.1704;+07030.9553;070813;202200	8/13/2007	15755
0008	DEV	0353	707110027500	-33.40284	-70.5159216666667	4:16:17 PM	DEV;0353;707110027500;-03324.1704;+07030.9553;070813;202200	8/13/2007	15756
0008	DEV	0354	692006249649	-33.40284	-70.5159216666667	4:16:17 PM	DEV;0354;692006249649;-03324.1704;+07030.9553;070813;202200	8/13/2007	15757
0008	DEV	0355	692006249383	-33.4028383333333	-70.5159166666667	4:16:18 PM	DEV;0355;692006249383;-03324.1703;+07030.9550;070813;202215	8/13/2007	15758
0008	DEV	0356	692006250678	-33.4028383333333	-70.515915	4:16:18 PM	DEV;0356;692006250678;-03324.1703;+07030.9549;070813;202230	8/13/2007	15759
0008	DEV	0357	B200389312527	-33.40284	-70.5159166666667	4:16:19 PM	DEV;0357;B200389312527;-03324.1704;+07030.9550;070813;202245	8/13/2007	15760
0008	DEV	0358	692006235697	-33.40284	-70.5159166666667	4:16:19 PM	DEV;0358;692006235697;-03324.1704;+07030.9550;070813;202245	8/13/2007	15761
0008	DEV	0359	692006267066	-33.4028433333333	-70.51592	4:16:20 PM	DEV;0359;692006267066;-03324.1706;+07030.9552;070813;202300	8/13/2007	15762
0008	DEV	0360	692006277455	-33.4028433333333	-70.51592	4:16:20 PM	DEV;0360;692006277455;-03324.1706;+07030.9552;070813;202300	8/13/2007	15763
0008	DEV	0361	80629146117	-33.402845	-70.5159233333333	4:16:20 PM	DEV;0361;80629146117;-03324.1707;+07030.9554;070813;202315	8/13/2007	15764

0008	DEV	0362	51200708055007234	-33.402845	-	4:16:20 PM	DEV;0362;51200708055007234;-03324.1707;+07030.9554;070813;202315	8/13/2007	15765
0008	DEV	0363	80630073166	-33.402845	-	4:16:20 PM	DEV;0363;80630073166;-03324.1707;+07030.9554;070813;202315	8/13/2007	15766
0008	DEV	0364	707110025584	-33.402845	-	4:16:20 PM	DEV;0364;707110025584;-03324.1707;+07030.9554;070813;202315	8/13/2007	15767
0008	DEV	0365	80629810173	-33.402845	-	4:16:20 PM	DEV;0365;80629810173;-03324.1707;+07030.9554;070813;202330	8/13/2007	15768
0008	DEV	0366	707110025565	-33.402845	-	4:16:20 PM	DEV;0366;707110025565;-03324.1707;+07030.9554;070813;202330	8/13/2007	15769
0008	DEV	0367	80629696001	-33.402845	-	4:16:20 PM	DEV;0367;80629696001;-03324.1707;+07030.9554;070813;202330	8/13/2007	15770
1234	EOT			0	0		EOT;1234;001164	8/13/2007 4:16:20 PM	15771
1234	SOT			0	0		SOT;1234	8/13/2007 4:21:17 PM	15772
0008	TRK	0368		-33.4028266666667	-	4:21:17 PM	TRK;0368;-03324.1696;+07030.9547;070813;202530	8/13/2007	15773
0008	TRK	0369		-33.4028383333333	-	4:21:17 PM	TRK;0369;-03324.1703;+07030.9556;070813;202730	8/13/2007	15774
0008	TRK	0370		-33.402895	-	4:21:17 PM	TRK;0370;-03324.1737;+07030.8459;070813;202945	8/13/2007	15775
1234	EOT			0	0		EOT;1234;000173	8/13/2007 4:21:18 PM	15776
1234	SOT			0	0		SOT;1234	8/13/2007 4:29:10 PM	15777
0008	DEV	0371	707110016356	-33.40291	-70.5141	4:29:10 PM	DEV;0371;707110016356;-03324.1746;+07030.8460;070813;203000	8/13/2007	15778
0008	DEV	0372	707110035532	-33.40291	-70.5141	4:29:10 PM	DEV;0372;707110035532;-03324.1746;+07030.8460;070813;203000	8/13/2007	15779
0008	DEV	0373	692006277182	-33.4029216666667	-	4:29:10 PM	DEV;0373;692006277182;-03324.1753;+07030.8458;070813;203030	8/13/2007	15780
0008	TRK	0374		-33.4024716666667	-70.5115	4:29:11 PM	TRK;0374;-03324.1483;+07030.6900;070813;203230	8/13/2007	15781
0008	DEV	0375	B200389441127	-33.4018366666667	-70.51053	4:29:11 PM	DEV;0375;B200389441127;-03324.1102;+07030.6318;070813;203315	8/13/2007	15782
0008	DEV	0376	80629951656	-33.40184	-	4:29:11 PM	DEV;0376;80629951656;-03324.1104;+07030.6316;070813;203330	8/13/2007	15783
0008	TRK	0377		-33.4020566666667	-	4:29:12 PM	TRK;0377;-03324.1234;+07030.6682;070813;203530	8/13/2007	15784
0008	DEV	0378	0708066152902100549310	-33.4020183333333	-70.51113	4:29:12 PM	DEV;0378;0708066152902100549310;-03324.1211;+07030.6678;070813;203615	8/13/2007	15785
0008	DEV	0379	692006240381	-33.4020183333333	-70.51113	4:29:12 PM	DEV;0379;692006240381;-03324.1211;+07030.6678;070813;203615	8/13/2007	15786
0008	DEV	0380	2027007800023	-33.4020183333333	-70.51113	4:29:12 PM	DEV;0380;2027007800023;-03324.1211;+07030.6678;070813;203615	8/13/2007	15787
0008	DEV	0381	0708066152902100499250	-33.4020183333333	-70.51113	4:29:12 PM	DEV;0381;0708066152902100499250;-03324.1211;+07030.6678;070813;203615	8/13/2007	15788
1234	EOT			0	0		EOT;1234;000695	8/13/2007 4:29:12 PM	15789
1234	SOT			0	0		SOT;1234	8/13/2007	15790

								4:36:29 PM	
0008	TRK	0382		-33.4019933333333	-70.511085	4:36:30 PM	TRK;0382;-03324.1196;+07030.6651;070813;203830	8/13/2007	15791
0008	DEV	0383	000035406578	-33.4020966666667	-70.5111666666667	4:36:30 PM	DEV;0383;000035406578;-03324.1258;+07030.6700;070813;204000	8/13/2007	15792
0008	TRK	0384		-33.402395	-70.5117483333333	4:36:30 PM	TRK;0384;-03324.1437;+07030.7049;070813;204100	8/13/2007	15793
0008	DEV	0385	2034962840010	-33.402365	-70.5117516666667	4:36:31 PM	DEV;0385;2034962840010;-03324.1419;+07030.7051;070813;204115	8/13/2007	15794
0008	DEV	0386	692006226022	-33.4023533333333	-70.511174	4:36:32 PM	DEV;0386;692006226022;-03324.1412;+07030.7044;070813;204130	8/13/2007	15795
0008	DEV	0387	692006286803	-33.4023416666667	-70.511173	4:36:32 PM	DEV;0387;692006286803;-03324.1405;+07030.7038;070813;204145	8/13/2007	15796
0008	DEV	0388	692006287658	-33.4023416666667	-70.511173	4:36:32 PM	DEV;0388;692006287658;-03324.1405;+07030.7038;070813;204145	8/13/2007	15797
0008	DEV	0389	692006256499	-33.402335	-70.5117233333333	4:36:32 PM	DEV;0389;692006256499;-03324.1401;+07030.7034;070813;204200	8/13/2007	15798
0008	DEV	0390	692006248767	-33.402325	-70.511171	4:36:32 PM	DEV;0390;692006248767;-03324.1395;+07030.7026;070813;204230	8/13/2007	15799
0008	DEV	0391	000035427354	-33.402325	-70.511171	4:36:32 PM	DEV;0391;000035427354;-03324.1395;+07030.7026;070813;204230	8/13/2007	15800
0008	DEV	0392	692006271919	-33.4023233333333	-70.5117066666667	4:36:32 PM	DEV;0392;692006271919;-03324.1394;+07030.7024;070813;204245	8/13/2007	15801
0008	DEV	0393	2037339120016	-33.4023233333333	-70.5117066666667	4:36:32 PM	DEV;0393;2037339120016;-03324.1394;+07030.7024;070813;204245	8/13/2007	15802
0008	TRK	0394		-33.4023216666667	-70.5116966666667	4:36:37 PM	TRK;0394;-03324.1393;+07030.7018;070813;204500	8/13/2007	15803
1234	EOT			0	0		EOT;1234;000785	8/13/2007 4:36:37 PM	15804
1234	SOT			0	0		SOT;1234	8/13/2007 4:43:07 PM	15805
0008	TRK	0395		-33.4026933333333	-70.5127316666667	4:43:08 PM	TRK;0395;-03324.1616;+07030.7639;070813;204645	8/13/2007	15806
0008	DEV	0396	800438923763	-33.40269	-70.51272	4:43:08 PM	DEV;0396;800438923763;-03324.1614;+07030.7632;070813;204700	8/13/2007	15807
0008	DEV	0397	000035427795	-33.40269	-70.51272	4:43:08 PM	DEV;0397;000035427795;-03324.1614;+07030.7632;070813;204700	8/13/2007	15808
0008	DEV	0398	6930347360	-33.4026866666667	-70.5127133333333	4:43:08 PM	DEV;0398;6930347360;-03324.1612;+07030.7628;070813;204715	8/13/2007	15809
0008	DEV	0399	692006130540	-33.4026866666667	-70.5127133333333	4:43:09 PM	DEV;0399;692006130540;-03324.1612;+07030.7628;070813;204715	8/13/2007	15810
0008	DEV	0400	B200389209725	-33.4026866666667	-70.5127133333333	4:43:09 PM	DEV;0400;B200389209725;-03324.1612;+07030.7628;070813;204715	8/13/2007	15811
0008	DEV	0401	692006127646	-33.4026816666667	-70.512715	4:43:10 PM	DEV;0401;692006127646;-03324.1609;+07030.7629;070813;204730	8/13/2007	15812
0008	DEV	0402	B2003899686@@@	-33.4026816666667	-70.512715	4:43:10 PM	DEV;0402;B2003899686@@@;-03324.1609;+07030.7629;070813;204730	8/13/2007	15813
0008	DEV	0403	51200708055007153	-33.4026816666667	-70.512715	4:43:11 PM	DEV;0403;51200708055007153;-03324.1609;+07030.7629;070813;204730	8/13/2007	15814
0008	DEV	0404	692006257612	-33.4026783333333	-70.5127166666667	4:43:11 PM	DEV;0404;692006257612;-03324.1607;+07030.7630;070813;204745	8/13/2007	15815

0008	DEV	0405	692006288425	- 33.4026783333333	- 70.5127166666667	4:43:12 PM	DEV;0405;692006288425;- 03324.1607;+07030.7630;070813;204745	8/13/2007	15816
0008	DEV	0406	692006285988	- 33.4026783333333	- 70.5127166666667	4:43:12 PM	DEV;0406;692006285988;- 03324.1607;+07030.7630;070813;204745	8/13/2007	15817
0008	DEV	0407	692006288667	- 33.4026783333333	- 70.5127166666667	4:43:12 PM	DEV;0407;692006288667;- 03324.1607;+07030.7630;070813;204745	8/13/2007	15818
0008	DEV	0408	692006266275	-33.402665	-70.512725	4:43:12 PM	DEV;0408;692006266275;- 03324.1599;+07030.7635;070813;204800	8/13/2007	15819
0008	DEV	0409	2035728920012	-33.402665	-70.512725	4:43:12 PM	DEV;0409;2035728920012;- 03324.1599;+07030.7635;070813;204800	8/13/2007	15820
0008	DEV	0410	0708066152902101822781	-33.402665	-70.512725	4:43:12 PM	DEV;0410;0708066152902101822781;- 03324.1599;+07030.7635;070813;204800	8/13/2007	15821
0008	DEV	0411	707110048945	-33.40266	- 70.5127266666667	4:43:12 PM	DEV;0411;707110048945;- 03324.1596;+07030.7636;070813;204815	8/13/2007	15822
0008	DEV	0412	707110039566	-33.40266	- 70.5127266666667	4:43:12 PM	DEV;0412;707110039566;- 03324.1596;+07030.7636;070813;204815	8/13/2007	15823
0008	DEV	0413	80629544236	-33.40266	- 70.5127266666667	4:43:12 PM	DEV;0413;80629544236;- 03324.1596;+07030.7636;070813;204815	8/13/2007	15824
0008	DEV	0414	707110010754	-33.40266	- 70.5127266666667	4:43:12 PM	DEV;0414;707110010754;- 03324.1596;+07030.7636;070813;204815	8/13/2007	15825
0008	TRK	0415		- 33.4026616666667	- 70.5127016666667	4:43:20 PM	TRK;0415;- 03324.1597;+07030.7621;070813;205015	8/13/2007	15826
1234	EOT			0	0		EOT;1234;001301	8/13/2007 4:43:20 PM	15827
1234	SOT			0	0		SOT;1234	8/13/2007 4:49:12 PM	15828
0008	TRK	0416		-33.40244	-70.513395	4:49:12 PM	TRK;0416;- 03324.1464;+07030.8037;070813;205230	8/13/2007	15829
0008	DEV	0417	0708066152902100559723	-33.402085	- 70.5135566666667	4:49:12 PM	DEV;0417;0708066152902100559723;- 03324.1251;+07030.8134;070813;205400	8/13/2007	15830
0008	TRK	0418		-33.402085	- 70.5135633333333	4:49:12 PM	TRK;0418;- 03324.1251;+07030.8138;070813;205500	8/13/2007	15831
0008	DEV	0419	692006238483	-33.40193	- 70.5135883333333	4:49:13 PM	DEV;0419;692006238483;- 03324.1158;+07030.8153;070813;205515	8/13/2007	15832
0008	DEV	0420	692006284440	- 33.4018966666667	-70.51357	4:49:13 PM	DEV;0420;692006284440;- 03324.1138;+07030.8142;070813;205530	8/13/2007	15833
0008	TRK	0421		- 33.4018283333333	- 70.5136366666667	4:49:13 PM	TRK;0421;- 03324.1097;+07030.8182;070813;205745	8/13/2007	15834
1234	EOT			0	0		EOT;1234;000366	8/13/2007 4:49:18 PM	15835
1234	SOT			0	0		SOT;1234	8/13/2007 4:55:19 PM	15836
0008	DEV	0422	0708066152902100478072	-33.4016	- 70.5135533333333	4:55:20 PM	DEV;0422;0708066152902100478072;- 03324.0960;+07030.8132;070813;205800	8/13/2007	15837
0008	DEV	0423	B200391496527	- 33.4013933333333	-70.51359	4:55:20 PM	DEV;0423;B200391496527;- 03324.0836;+07030.8154;070813;205930	8/13/2007	15838
0008	TRK	0424		- 33.4014166666667	- 70.5135766666667	4:55:20 PM	TRK;0424;- 03324.0850;+07030.8146;070813;210030	8/13/2007	15839
0008	TRK	0425		-33.40087	- 70.5135066666667	4:55:21 PM	TRK;0425;- 03324.0522;+07030.8104;070813;210230	8/13/2007	15840
0008	DEV	0426	692006280519	-33.40087	-	4:55:21 PM	DEV;0426;692006280519;-	8/13/2007	15841

					70.5135066666667		03324.0522;+07030.8104;070813;210230		
1234	EOT			0	0		EOT;1234;000319	8/13/2007 4:55:21 PM	15842
1234	SOT			0	0		SOT;1234	8/13/2007 5:01:24 PM	15843
0008	TRK	0427		- 33.4036933333333	- 70.5133616666667	5:01:25 PM	TRK;0427;- 03324.2216;+07030.8017;070813;210430	8/13/2007	15844
0008	DEV	0428	2041089060018	- 33.4037383333333	- 70.5135683333333	5:01:25 PM	DEV;0428;2041089060018;- 03324.2243;+07030.8141;070813;210445	8/13/2007	15845
0008	DEV	0429	B2003908982@@@@	- 33.4042083333333	- 70.5141066666667	5:01:25 PM	DEV;0429;B2003908982@@@@;- 03324.2525;+07030.8464;070813;210615	8/13/2007	15846
0008	TRK	0430		- 33.4042483333333	-70.51415	5:01:26 PM	TRK;0430;- 03324.2549;+07030.8490;070813;210715	8/13/2007	15847
0008	DEV	0431	692006233579	- 33.4044966666667	-70.51446	5:01:26 PM	DEV;0431;692006233579;- 03324.2698;+07030.8676;070813;210815	8/13/2007	15848
0008	DEV	0432	692006238204	- 33.4046783333333	- 70.5146083333333	5:01:26 PM	DEV;0432;692006238204;- 03324.2807;+07030.8765;070813;210845	8/13/2007	15849
0008	TRK	0433		-33.40469	-70.51461	5:01:26 PM	TRK;0433;- 03324.2814;+07030.8766;070813;211000	8/13/2007	15850
1234	EOT			0	0		EOT;1234;000421	8/13/2007 5:01:26 PM	15851
1234	SOT			0	0		SOT;1234	8/13/2007 5:09:03 PM	15852
0008	DEV	0434	2040234530032	- 33.4054766666667	- 70.5158333333333	5:09:04 PM	DEV;0434;2040234530032;- 03324.3286;+07030.9500;070813;211130	8/13/2007	15853
0008	TRK	0435		- 33.4054516666667	- 70.5158233333333	5:09:04 PM	TRK;0435;- 03324.3271;+07030.9494;070813;211230	8/13/2007	15854
0008	DEV	0436	692006273769	- 33.4049216666667	-70.51567	5:09:04 PM	DEV;0436;692006273769;- 03324.2953;+07030.9402;070813;211430	8/13/2007	15855
0008	DEV	0437	51200708050115470	- 33.4049216666667	- 70.5156816666667	5:09:05 PM	DEV;0437;51200708050115470;- 03324.2953;+07030.9409;070813;211445	8/13/2007	15856
0008	TRK	0438		-33.404955	-70.515725	5:09:05 PM	TRK;0438;- 03324.2973;+07030.9435;070813;211545	8/13/2007	15857
0008	DEV	0439	80630032028	-33.40439	- 70.5152266666667	5:09:05 PM	DEV;0439;80630032028;- 03324.2634;+07030.9136;070813;211615	8/13/2007	15858
1234	EOT			0	0		EOT;1234;000374	8/13/2007 5:09:10 PM	15859
1234	SOT			0	0		SOT;1234	8/13/2007 5:17:22 PM	15860
0008	DEV	0440	692006242632	-33.403845	-70.51481	5:17:22 PM	DEV;0440;692006242632;- 03324.2307;+07030.8886;070813;211800	8/13/2007	15861
0008	TRK	0441		- 33.4039066666667	- 70.5147983333333	5:17:23 PM	TRK;0441;- 03324.2344;+07030.8879;070813;211900	8/13/2007	15862
0008	DEV	0442	692006248377	- 33.4035116666667	- 70.5149633333333	5:17:23 PM	DEV;0442;692006248377;- 03324.2107;+07030.8978;070813;211930	8/13/2007	15863
0008	DEV	0443	0708066152902100511732	- 33.4030266666667	- 70.5151416666667	5:17:24 PM	DEV;0443;0708066152902100511732;- 03324.1816;+07030.9085;070813;212115	8/13/2007	15864
0008	TRK	0444		- 33.4030233333333	-70.51508	5:17:24 PM	TRK;0444;- 03324.1814;+07030.9048;070813;212215	8/13/2007	15865
0008	DEV	0445	692006253737	- 33.4035033333333	- 70.5150283333333	5:17:25 PM	DEV;0445;692006253737;- 03324.2102;+07030.9017;070813;212245	8/13/2007	15866

0008	DEV	0446	692006228082	-33.40353	70.5150266666667	5:17:25 PM	DEV;0446;692006228082;-03324.2118;+07030.9016;070813;212300	8/13/2007	15867
0008	DEV	0447	51200708060060690	-33.40403	70.5149783333333	5:17:25 PM	DEV;0447;51200708060060690;-03324.2418;+07030.8987;070813;212430	8/13/2007	15868
0008	TRK	0448		-33.4040233333333	-70.514955	5:17:25 PM	TRK;0448;-03324.2414;+07030.8973;070813;212545	8/13/2007	15869
1234	EOT			0	0		EOT;1234;000554	8/13/2007 5:17:25 PM	15870
1234	SOT			0	0		SOT;1234	8/13/2007 5:25:24 PM	15871
0008	DEV	0449	8062923427K	-33.40414	-70.515255	5:25:25 PM	DEV;0449;8062923427K;-03324.2484;+07030.9153;070813;212615	8/13/2007	15872
0008	DEV	0450	692006277168	-33.4041616666667	70.5153516666667	5:25:25 PM	DEV;0450;692006277168;-03324.2497;+07030.9211;070813;212815	8/13/2007	15873
0008	DEV	0451	692006289460	-33.40431	70.5157316666667	5:25:25 PM	DEV;0451;692006289460;-03324.2586;+07030.9439;070813;212915	8/13/2007	15874
0008	TRK	0452		-33.4043833333333	70.5160033333333	5:25:26 PM	TRK;0452;-03324.2630;+07030.9602;070813;213015	8/13/2007	15875
0008	DEV	0453	B200389187927	-33.4055433333333	70.5159583333333	5:25:26 PM	DEV;0453;B200389187927;-03324.3326;+07030.9575;070813;213130	8/13/2007	15876
0008	TRK	0454		-33.405515	70.5159583333333	5:25:26 PM	TRK;0454;-03324.3309;+07030.9575;070813;213230	8/13/2007	15877
1234	EOT			0	0		EOT;1234;000369	8/13/2007 5:25:31 PM	15878
1234	SOT			0	0		SOT;1234	8/13/2007 5:33:59 PM	15879
0008	DEV	0455	692006118253	-33.4060533333333	-70.51547	5:34:00 PM	DEV;0455;692006118253;-03324.3632;+07030.9282;070813;213430	8/13/2007	15880
0008	TRK	0456		-33.4060566666667	70.5154333333333	5:34:00 PM	TRK;0456;-03324.3634;+07030.9260;070813;213545	8/13/2007	15881
0008	DEV	0457	800438914321	-33.4057983333333	-70.514865	5:34:01 PM	DEV;0457;800438914321;-03324.3479;+07030.8919;070813;213730	8/13/2007	15882
0008	DEV	0458	B200389610927	-33.4057966666667	-70.514855	5:34:01 PM	DEV;0458;B200389610927;-03324.3478;+07030.8913;070813;213745	8/13/2007	15883
0008	DEV	0459	B200389356525	-33.4057966666667	-70.514855	5:34:02 PM	DEV;0459;B200389356525;-03324.3478;+07030.8913;070813;213745	8/13/2007	15884
0008	DEV	0460	707110005401	-33.4057966666667	-70.514855	5:34:02 PM	DEV;0460;707110005401;-03324.3478;+07030.8913;070813;213745	8/13/2007	15885
0008	DEV	0461	B200391169225	-33.4058	70.5148516666667	5:34:03 PM	DEV;0461;B200391169225;-03324.3480;+07030.8911;070813;213800	8/13/2007	15886
0008	DEV	0462	692006225068	-33.4058	70.5148516666667	5:34:03 PM	DEV;0462;692006225068;-03324.3480;+07030.8911;070813;213800	8/13/2007	15887
0008	DEV	0463	692006229758	-33.4058	70.5148516666667	5:34:03 PM	DEV;0463;692006229758;-03324.3480;+07030.8911;070813;213800	8/13/2007	15888
0008	DEV	0464	692006275991	-33.40581	70.5148533333333	5:34:03 PM	DEV;0464;692006275991;-03324.3486;+07030.8912;070813;213815	8/13/2007	15889
0008	DEV	0465	7802600133217	-33.4058183333333	70.5148583333333	5:34:03 PM	DEV;0465;7802600133217;-03324.3491;+07030.8915;070813;213845	8/13/2007	15890
0008	TRK	0466		-33.4058333333333	70.5148633333333	5:34:03 PM	TRK;0466;-03324.3500;+07030.8918;070813;214015	8/13/2007	15891
0008	TRK	0467		-33.405795	-	5:34:08 PM	TRK;0467;-	8/13/2007	15892

					70.5150166666667		03324.3477;+07030.9010;070813;214230		
1234	EOT			0	0		EOT;1234;000787	8/13/2007 5:34:08 PM	15893
1234	SOT			0	0		SOT;1234	8/13/2007 5:40:34 PM	15894
0008	DEV	0468	51200708065002559	- 33.4054533333333	- 70.5146433333333	5:40:35 PM	DEV;0468;51200708065002559;- 03324.3272;+07030.8786;070813;214345	8/13/2007	15895
0008	DEV	0469	692006246593	- 33.4054533333333	- 70.5146433333333	5:40:35 PM	DEV;0469;692006246593;- 03324.3272;+07030.8786;070813;214345	8/13/2007	15896
0008	TRK	0470		- 33.4054716666667	-70.514585	5:40:35 PM	TRK;0470;- 03324.3283;+07030.8751;070813;214445	8/13/2007	15897
1234	SOT			0	0		SOT;1234	8/13/2007 5:48:29 PM	15898
0008	DEV	0468	51200708065002559	- 33.4054533333333	- 70.5146433333333	5:48:29 PM	DEV;0468;51200708065002559;- 03324.3272;+07030.8786;070813;214345	8/13/2007	15899
0008	DEV	0469	692006246593	- 33.4054533333333	- 70.5146433333333	5:48:29 PM	DEV;0469;692006246593;- 03324.3272;+07030.8786;070813;214345	8/13/2007	15900
0008	TRK	0470		- 33.4054716666667	-70.514585	5:48:29 PM	TRK;0470;- 03324.3283;+07030.8751;070813;214445	8/13/2007	15901
0008	TRK	0471		- 33.4054833333333	- 70.5141916666667	5:48:29 PM	TRK;0471;- 03324.3290;+07030.8515;070813;214645	8/13/2007	15902
0008	DEV	0472	707110034412	-33.40548	- 70.5141966666667	5:48:30 PM	DEV;0472;707110034412;- 03324.3288;+07030.8518;070813;214745	8/13/2007	15903
0008	DEV	0473	800438918565	-33.405055	- 70.5136733333333	5:48:30 PM	DEV;0473;800438918565;- 03324.3033;+07030.8204;070813;214945	8/13/2007	15904
0008	DEV	0474	B200389889027	-33.40505	-70.513675	5:48:31 PM	DEV;0474;B200389889027;- 03324.3030;+07030.8205;070813;215000	8/13/2007	15905
0008	DEV	0475	707110006856	-33.40505	-70.513675	5:48:31 PM	DEV;0475;707110006856;- 03324.3030;+07030.8205;070813;215000	8/13/2007	15906
0008	DEV	0476	692006282283	-33.405045	- 70.5136783333333	5:48:32 PM	DEV;0476;692006282283;- 03324.3027;+07030.8207;070813;215015	8/13/2007	15907
0008	DEV	0477	692006240835	-33.405045	- 70.5136783333333	5:48:32 PM	DEV;0477;692006240835;- 03324.3027;+07030.8207;070813;215015	8/13/2007	15908
0008	DEV	0478	692006244566	-33.405045	- 70.5136783333333	5:48:33 PM	DEV;0478;692006244566;- 03324.3027;+07030.8207;070813;215015	8/13/2007	15909
0008	DEV	0479	707110042011	-33.40504	- 70.5136833333333	5:48:33 PM	DEV;0479;707110042011;- 03324.3024;+07030.8210;070813;215030	8/13/2007	15910
0008	DEV	0480	000035421285	-33.40504	- 70.5136833333333	5:48:33 PM	DEV;0480;000035421285;- 03324.3024;+07030.8210;070813;215030	8/13/2007	15911
0008	DEV	0481	800438918565	-33.40504	- 70.5136833333333	5:48:33 PM	DEV;0481;800438918565;- 03324.3024;+07030.8210;070813;215030	8/13/2007	15912
0008	TRK	0482		-33.405035	- 70.5136966666667	5:48:33 PM	TRK;0482;- 03324.3021;+07030.8218;070813;215130	8/13/2007	15913
0008	TRK	0483		- 33.4049866666667	- 70.5138116666667	5:48:33 PM	TRK;0483;- 03324.2992;+07030.8287;070813;215330	8/13/2007	15914
0008	DEV	0484	800438932849	-33.405065	- 70.5136983333333	5:48:33 PM	DEV;0484;800438932849;- 03324.3039;+07030.8219;070813;215345	8/13/2007	15915
0008	DEV	0485	0708066152902100445659	- 33.4045566666667	-70.513325	5:48:33 PM	DEV;0485;0708066152902100445659;- 03324.2734;+07030.7995;070813;215530	8/13/2007	15916
0008	DEV	0486	692006129767	- 33.4045633333333	- 70.5133433333333	5:48:33 PM	DEV;0486;692006129767;- 03324.2738;+07030.8006;070813;215545	8/13/2007	15917

0008	DEV	0487	800437640829	- 33.4045633333333	- 70.5133433333333	5:48:33 PM	DEV;0487;800437640829;- 03324.2738;+07030.8006;070813;215545	8/13/2007	15918
0008	TRK	0488		- 33.4045666666667	- 70.5134683333333	5:48:38 PM	TRK;0488;- 03324.2740;+07030.8081;070813;215700	8/13/2007	15919
1234	EOT			0	0		EOT;1234;001261	8/13/2007 5:48:38 PM	15920
1234	SOT			0	0		SOT;1234	8/13/2007 5:57:22 PM	15921
0008	DEV	0489	51200708010167400	- 33.4043416666667	- 70.5132583333333	5:57:23 PM	DEV;0489;51200708010167400;- 03324.2605;+07030.7955;070813;215830	8/13/2007	15922
0008	TRK	0490		- 33.4044166666667	-70.513345	5:57:23 PM	TRK;0490;- 03324.2650;+07030.8007;070813;215930	8/13/2007	15923
0008	DEV	0491	692006157429	-33.40422	-70.513045	5:57:24 PM	DEV;0491;692006157429;- 03324.2532;+07030.7827;070813;220030	8/13/2007	15924
0008	DEV	0492	2036776300016	- 33.4041783333333	- 70.5129966666667	5:57:24 PM	DEV;0492;2036776300016;- 03324.2507;+07030.7798;070813;220230	8/13/2007	15925
0008	DEV	0493	0708036152902100559095	- 33.4041783333333	- 70.5129966666667	5:57:24 PM	DEV;0493;0708036152902100559095;- 03324.2507;+07030.7798;070813;220230	8/13/2007	15926
0008	TRK	0494		- 33.4041166666667	- 70.5129883333333	5:57:24 PM	TRK;0494;- 03324.2470;+07030.7793;070813;220330	8/13/2007	15927
0008	DEV	0495	707110047917	- 33.4036233333333	- 70.5122016666667	5:57:25 PM	DEV;0495;707110047917;- 03324.2174;+07030.7321;070813;220415	8/13/2007	15928
0008	DEV	0496	692006266178	- 33.4036366666667	- 70.5121983333333	5:57:25 PM	DEV;0496;692006266178;- 03324.2182;+07030.7319;070813;220430	8/13/2007	15929
0008	DEV	0497	B200390211527	- 33.4036366666667	- 70.5121983333333	5:57:25 PM	DEV;0497;B200390211527;- 03324.2182;+07030.7319;070813;220430	8/13/2007	15930
0008	DEV	0498	2027510280028	- 33.4036366666667	- 70.5121983333333	5:57:25 PM	DEV;0498;2027510280028;- 03324.2182;+07030.7319;070813;220430	8/13/2007	15931
0008	DEV	0499	692006119228	- 33.4036366666667	- 70.5121983333333	5:57:25 PM	DEV;0499;692006119228;- 03324.2182;+07030.7319;070813;220430	8/13/2007	15932
1234	EOT			0	0		EOT;1234;000692	8/13/2007 5:57:25 PM	15933
1234	SOT			0	0		SOT;1234	8/13/2007 6:04:13 PM	15934
0008	DEV	0500	692006160091	- 33.4033283333333	- 70.5117783333333	6:04:14 PM	DEV;0500;692006160091;- 03324.1997;+07030.7067;070813;220600	8/13/2007	15935
0008	TRK	0501		-33.40323	-70.5118	6:04:14 PM	TRK;0501;- 03324.1938;+07030.7080;070813;220715	8/13/2007	15936
0008	DEV	0502	B2003911414@@@@	- 33.4032516666667	- 70.5117733333333	6:04:14 PM	DEV;0502;B2003911414@@@@;- 03324.1951;+07030.7064;070813;220800	8/13/2007	15937
0008	TRK	0503		- 33.4030216666667	- 70.5113433333333	6:04:14 PM	TRK;0503;- 03324.1813;+07030.6806;070813;221000	8/13/2007	15938
0008	DEV	0504	B200387243921	- 33.4029566666667	- 70.5112683333333	6:04:15 PM	DEV;0504;B200387243921;- 03324.1774;+07030.6761;070813;221030	8/13/2007	15939
0008	DEV	0505	692006134160	-33.40314	- 70.5115283333333	6:04:15 PM	DEV;0505;692006134160;- 03324.1884;+07030.6917;070813;221230	8/13/2007	15940
1234	EOT			0	0		EOT;1234;000373	8/13/2007 6:04:19 PM	15941
1234	SOT			0	0		SOT;1234	8/13/2007 6:10:53 PM	15942
0008	DEV	0506	692006151113	-	-	6:10:54 PM	DEV;0506;692006151113;-	8/13/2007	15943

				33.4031833333333	70.5115533333333		03324.1910;+07030.6932;070813;221400		
0008	DEV	0507	692006151807	- 33.4031833333333	- 70.5115533333333	6:10:54 PM	DEV;0507;692006151807;- 03324.1910;+07030.6932;070813;221400	8/13/2007	15944
0008	TRK	0508		- 33.4031516666667	-70.511525	6:10:54 PM	TRK;0508;- 03324.1891;+07030.6915;070813;221415	8/13/2007	15945
0008	DEV	0509	692006120740	-33.40309	-70.51144	6:10:55 PM	DEV;0509;692006120740;- 03324.1854;+07030.6864;070813;221530	8/13/2007	15946
0008	TRK	0510		- 33.4027883333333	-70.51057	6:10:55 PM	TRK;0510;- 03324.1673;+07030.6342;070813;221630	8/13/2007	15947
0008	DEV	0511	707110010819	- 33.4027883333333	-70.51057	6:10:56 PM	DEV;0511;707110010819;- 03324.1673;+07030.6342;070813;221630	8/13/2007	15948
0008	DEV	0512	0708066152902100385848	- 33.4028033333333	-70.51062	6:10:56 PM	DEV;0512;0708066152902100385848;- 03324.1682;+07030.6372;070813;221645	8/13/2007	15949
0008	DEV	0513	692006274828	- 33.4028033333333	-70.51062	6:10:56 PM	DEV;0513;692006274828;- 03324.1682;+07030.6372;070813;221645	8/13/2007	15950
0008	DEV	0514	692006226850	- 33.4028033333333	-70.51062	6:10:56 PM	DEV;0514;692006226850;- 03324.1682;+07030.6372;070813;221645	8/13/2007	15951
0008	DEV	0515	80629402555	- 33.4028033333333	-70.51062	6:10:56 PM	DEV;0515;80629402555;- 03324.1682;+07030.6372;070813;221645	8/13/2007	15952
0008	DEV	0516	707110011704	- 33.4028066666667	- 70.5106566666667	6:10:57 PM	DEV;0516;707110011704;- 03324.1684;+07030.6394;070813;221700	8/13/2007	15953
0008	DEV	0517	B2003911543@@@	- 33.4028066666667	- 70.5106566666667	6:10:57 PM	DEV;0517;B2003911543@@@;- 03324.1684;+07030.6394;070813;221700	8/13/2007	15954
0008	DEV	0518	2022699640019	- 33.4028066666667	- 70.5106566666667	6:11:01 PM	DEV;0518;2022699640019;- 03324.1684;+07030.6394;070813;221700	8/13/2007	15955
0008	TRK	0519		- 33.4026716666667	- 70.5101133333333	6:11:01 PM	TRK;0519;- 03324.1603;+07030.6068;070813;221915	8/13/2007	15956
1234	EOT			0	0		EOT;1234;000857	8/13/2007 6:11:01 PM	15957
1234	SOT			0	0		SOT;1234	8/13/2007 6:15:53 PM	15958
0008	TRK	0520		- 33.4038633333333	- 70.5128483333333	6:15:54 PM	TRK;0520;- 03324.2318;+07030.7709;070813;222100	8/13/2007	15959
0008	TRK	0521		- 33.4051366666667	- 70.5120533333333	6:15:54 PM	TRK;0521;- 03324.3082;+07030.7232;070813;222300	8/13/2007	15960
1234	EOT			0	0		EOT;1234;000125	8/13/2007 6:15:54 PM	15961
1234	SOT			0	0		SOT;1234	8/13/2007 6:24:19 PM	15962
0008	DEV	0522	B200389790827	-33.405205	- 70.5121083333333	6:24:20 PM	DEV;0522;B200389790827;- 03324.3123;+07030.7265;070813;222445	8/13/2007	15963
0008	DEV	0523	692006189501	-33.405205	- 70.5121083333333	6:24:20 PM	DEV;0523;692006189501;- 03324.3123;+07030.7265;070813;222445	8/13/2007	15964
0008	DEV	0524	692006135154	-33.405205	- 70.5121083333333	6:24:20 PM	DEV;0524;692006135154;- 03324.3123;+07030.7265;070813;222445	8/13/2007	15965
0008	DEV	0525	0708066152902100160431	-33.405205	- 70.5121083333333	6:24:21 PM	DEV;0525;0708066152902100160431;- 03324.3123;+07030.7265;070813;222445	8/13/2007	15966
0008	DEV	0526	B200390927427	- 33.4052133333333	-70.512085	6:24:22 PM	DEV;0526;B200390927427;- 03324.3128;+07030.7251;070813;222500	8/13/2007	15967
0008	DEV	0527	B200391426127	- 33.4052133333333	-70.512085	6:24:22 PM	DEV;0527;B200391426127;- 03324.3128;+07030.7251;070813;222500	8/13/2007	15968

0008	DEV	0528	80630526705	-33.4052133333333	-70.512085	6:24:23 PM	DEV;0528;80630526705;-03324.3128;+07030.7251;070813;222500	8/13/2007	15969
0008	DEV	0529	692006241251	-33.4052133333333	-70.512085	6:24:23 PM	DEV;0529;692006241251;-03324.3128;+07030.7251;070813;222500	8/13/2007	15970
0008	DEV	0530	707110042005	-33.4052133333333	-70.512065	6:24:23 PM	DEV;0530;707110042005;-03324.3128;+07030.7239;070813;222515	8/13/2007	15971
0008	DEV	0531	692006241251	-33.40521	-70.5120533333333	6:24:23 PM	DEV;0531;692006241251;-03324.3126;+07030.7232;070813;222530	8/13/2007	15972
0008	DEV	0532	80629810718	-33.40521	-70.5120533333333	6:24:23 PM	DEV;0532;80629810718;-03324.3126;+07030.7232;070813;222530	8/13/2007	15973
0008	DEV	0533	707110030184	-33.40521	-70.5120383333333	6:24:23 PM	DEV;0533;707110030184;-03324.3126;+07030.7223;070813;222545	8/13/2007	15974
0008	DEV	0534	707110041908	-33.40521	-70.5120383333333	6:24:25 PM	DEV;0534;707110041908;-03324.3126;+07030.7223;070813;222545	8/13/2007	15975
0008	DEV	0535	707110046918	-33.40521	-70.5120383333333	6:24:25 PM	DEV;0535;707110046918;-03324.3126;+07030.7223;070813;222545	8/13/2007	15976
0008	DEV	0536	00668676	-33.40521	-70.5120383333333	6:24:25 PM	DEV;0536;00668676;-03324.3126;+07030.7223;070813;222545	8/13/2007	15977
0008	DEV	0537	00670821	-33.4052083333333	-70.512025	6:24:25 PM	DEV;0537;00670821;-03324.3125;+07030.7215;070813;222600	8/13/2007	15978
0008	DEV	0538	80629124148	-33.4052083333333	-70.512025	6:24:26 PM	DEV;0538;80629124148;-03324.3125;+07030.7215;070813;222600	8/13/2007	15979
0008	DEV	0539	B200389539925	-33.4052083333333	-70.512025	6:24:26 PM	DEV;0539;B200389539925;-03324.3125;+07030.7215;070813;222600	8/13/2007	15980
0008	DEV	0540	692006241251	-33.40521	-70.51201	6:24:26 PM	DEV;0540;692006241251;-03324.3126;+07030.7206;070813;222615	8/13/2007	15981
0008	DEV	0541	707110042005	-33.40521	-70.51201	6:24:26 PM	DEV;0541;707110042005;-03324.3126;+07030.7206;070813;222615	8/13/2007	15982
0008	TRK	0542		-33.40517	-70.5118666666667	6:24:26 PM	TRK;0542;-03324.3102;+07030.7120;070813;222715	8/13/2007	15983
0008	TRK	0543		-33.4059833333333	-70.51144	6:24:26 PM	TRK;0543;-03324.3590;+07030.6864;070813;222915	8/13/2007	15984
0008	DEV	0544	707110021121	-33.4059916666667	-70.5114483333333	6:24:26 PM	DEV;0544;707110021121;-03324.3595;+07030.6869;070813;222945	8/13/2007	15985
0008	DEV	0545	692006285251	-33.4059966666667	-70.5114516666667	6:24:26 PM	DEV;0545;692006285251;-03324.3598;+07030.6871;070813;223000	8/13/2007	15986
0008	DEV	0546	692006289770	-33.4059966666667	-70.5114516666667	6:24:26 PM	DEV;0546;692006289770;-03324.3598;+07030.6871;070813;223000	8/13/2007	15987
0008	DEV	0547	692006230396	-33.4059966666667	-70.5114516666667	6:24:27 PM	DEV;0547;692006230396;-03324.3598;+07030.6871;070813;223000	8/13/2007	15988
0008	DEV	0548	80628999264	-33.4059966666667	-70.5114516666667	6:24:27 PM	DEV;0548;80628999264;-03324.3598;+07030.6871;070813;223000	8/13/2007	15989
0008	DEV	0549	80628719725	-33.406	-70.5114583333333	6:24:27 PM	DEV;0549;80628719725;-03324.3600;+07030.6875;070813;223015	8/13/2007	15990
0008	DEV	0550	00669907	-33.406	-70.5114583333333	6:24:27 PM	DEV;0550;00669907;-03324.3600;+07030.6875;070813;223015	8/13/2007	15991
0008	DEV	0551	51200708050123740	-33.406	-70.5114583333333	6:24:27 PM	DEV;0551;51200708050123740;-03324.3600;+07030.6875;070813;223015	8/13/2007	15992
0008	DEV	0552	0708066152902100498617	-33.406	-70.5114583333333	6:24:27 PM	DEV;0552;0708066152902100498617;-03324.3600;+07030.6875;070813;223015	8/13/2007	15993
0008	DEV	0553	000035422066	-	-70.51146	6:24:31 PM	DEV;0553;000035422066;-	8/13/2007	15994

				33.4060033333333			03324.3602;+07030.6876;070813;223030		
0008	DEV	0554	8063055749K	-33.4060033333333	-70.51146	6:24:31 PM	DEV;0554;8063055749K;- 03324.3602;+07030.6876;070813;223030	8/13/2007	15995
0008	DEV	0555	0708066152902100189166	-33.4060033333333	-70.51146	6:24:31 PM	DEV;0555;0708066152902100189166;- 03324.3602;+07030.6876;070813;223030	8/13/2007	15996
0008	TRK	0556		-33.4063483333333	-70.51111	6:24:31 PM	TRK;0556;- 03324.3809;+07030.6666;070813;223245	8/13/2007	15997
1234	EOT			0	0		EOT;1234;002146	8/13/2007 6:24:31 PM	15998
1234	SOT			0	0		SOT;1234	8/13/2007 6:31:20 PM	15999
0008	TRK	0557		-33.406865	-70.5108333333333	6:31:21 PM	TRK;0557;- 03324.4119;+07030.6500;070813;223430	8/13/2007	16000
0008	DEV	0558	B200389404327	-33.40682	-70.510885	6:31:21 PM	DEV;0558;B200389404327;- 03324.4092;+07030.6531;070813;223530	8/13/2007	16001
0008	DEV	0559	51200708050123341	-33.40682	-70.510885	6:31:21 PM	DEV;0559;51200708050123341;- 03324.4092;+07030.6531;070813;223530	8/13/2007	16002
0008	DEV	0560	80630291023	-33.4068133333333	-70.510885	6:31:21 PM	DEV;0560;80630291023;- 03324.4088;+07030.6531;070813;223545	8/13/2007	16003
0008	DEV	0561	692006232493	-33.40681	-70.51089	6:31:22 PM	DEV;0561;692006232493;- 03324.4086;+07030.6534;070813;223600	8/13/2007	16004
0008	DEV	0562	692006289156	-33.40681	-70.51089	6:31:22 PM	DEV;0562;692006289156;- 03324.4086;+07030.6534;070813;223600	8/13/2007	16005
0008	DEV	0563	692006225298	-33.40681	-70.51089	6:31:22 PM	DEV;0563;692006225298;- 03324.4086;+07030.6534;070813;223600	8/13/2007	16006
0008	DEV	0564	692006244333	-33.40681	-70.510895	6:31:22 PM	DEV;0564;692006244333;- 03324.4086;+07030.6537;070813;223615	8/13/2007	16007
0008	TRK	0565		-33.405025	-70.5120066666667	6:31:22 PM	TRK;0565;- 03324.3015;+07030.7204;070813;223830	8/13/2007	16008
1234	EOT			0	0		EOT;1234;000557	8/13/2007 6:31:27 PM	16009
1234	SOT			0	0		SOT;1234	8/13/2007 6:36:22 PM	16010
0008	TRK	0566		-33.4030766666667	-70.5131733333333	6:36:22 PM	TRK;0566;- 03324.1846;+07030.7904;070813;224045	8/13/2007	16011
0008	TRK	0567		-33.403075	-70.5228116666667	6:36:23 PM	TRK;0567;- 03324.1845;+07031.3687;070813;224230	8/13/2007	16012
0008	TRK	0568		-33.4076233333333	-70.5376066666667	6:36:23 PM	TRK;0568;- 03324.4574;+07032.2564;070813;224445	8/13/2007	16013
1234	EOT			0	0		EOT;1234;000173	8/13/2007 6:36:23 PM	16014
1234	SOT			0	0		SOT;1234	8/13/2007 6:41:22 PM	16015
0008	TRK	0569		-33.409115	-70.5422983333333	6:41:22 PM	TRK;0569;- 03324.5469;+07032.5379;070813;224630	8/13/2007	16016
0008	TRK	0570		-33.415685	-70.5394	6:41:22 PM	TRK;0570;- 03324.9411;+07032.3640;070813;224830	8/13/2007	16017
1234	EOT			0	0		EOT;1234;000125	8/13/2007 6:41:23 PM	16018
1234	SOT			0	0		SOT;1234	8/13/2007 6:46:21 PM	16019

0008	TRK	0571		-33.423155	-	6:46:22 PM	TRK;0571;- 03325.3893;+07032.2777;070813;225030	8/13/2007	16020
0008	TRK	0572		-	-	6:46:22 PM	TRK;0572;- 03325.9231;+07032.3459;070813;225230	8/13/2007	16021
0008	TRK	0573		-33.439855	-70.54329	6:46:22 PM	TRK;0573;- 03326.3913;+07032.5974;070813;225445	8/13/2007	16022
1234	EOT			0	0		EOT;1234;000173	8/13/2007 6:46:22 PM	16023
1234	SOT			0	0		SOT;1234	8/13/2007 6:51:22 PM	16024
0008	TRK	0574		-	-	6:51:23 PM	TRK;0574;- 03327.0617;+07032.6291;070813;225630	8/13/2007	16025
0008	TRK	0575		-	-	6:51:23 PM	TRK;0575;- 03327.4630;+07032.7269;070813;225830	8/13/2007	16026
1234	EOT			0	0		EOT;1234;000125	8/13/2007 6:51:23 PM	16027
1234	SOT			0	0		SOT;1234	8/13/2007 6:56:24 PM	16028
0008	TRK	0576		-	-	6:56:24 PM	TRK;0576;- 03327.7549;+07033.2803;070813;230030	8/13/2007	16029
0008	TRK	0577		-33.46069	-	6:56:24 PM	TRK;0577;- 03327.6414;+07034.0592;070813;230230	8/13/2007	16030
0008	TRK	0578		-	-70.571985	6:56:25 PM	TRK;0578;- 03327.5458;+07034.3191;070813;230445	8/13/2007	16031
1234	EOT			0	0		EOT;1234;000173	8/13/2007 6:56:25 PM	16032
1234	SOT			0	0		SOT;1234	8/13/2007 7:01:23 PM	16033
0008	TRK	0579		-33.465	-	7:01:24 PM	TRK;0579;- 03327.9000;+07034.4989;070813;230630	8/13/2007	16034
0008	TRK	0580		-33.468765	-70.576565	7:01:24 PM	TRK;0580;- 03328.1259;+07034.5939;070813;230830	8/13/2007	16035
1234	EOT			0	0		EOT;1234;000125	8/13/2007 7:01:24 PM	16036
1234	SOT			0	0		SOT;1234	8/13/2007 7:06:25 PM	16037
0008	TRK	0581		-33.47326	-	7:06:25 PM	TRK;0581;- 03328.3956;+07035.2544;070813;231045	8/13/2007	16038
0008	TRK	0582		-33.473635	-	7:06:26 PM	TRK;0582;- 03328.4181;+07036.0680;070813;231245	8/13/2007	16039
0008	TRK	0583		-	-	7:06:26 PM	TRK;0583;- 03328.5029;+07036.8434;070813;231500	8/13/2007	16040
1234	EOT			0	0		EOT;1234;000173	8/13/2007 7:06:26 PM	16041
1234	SOT			0	0		SOT;1234	8/13/2007 7:16:35 PM	16042
0008	TRK	0584		-	-70.61208	7:16:36 PM	TRK;0584;- 03329.2820;+07036.7248;070813;231645	8/13/2007	16043
0008	TRK	0585		-	-	7:16:36 PM	TRK;0585;- 03329.3060;+07036.6824;070813;231844	8/13/2007	16044
0008	TRK	0586		-	-	7:16:36 PM	TRK;0586;-	8/13/2007	16045

				33.4884333333333	70.6113733333333		03329.3060;+07036.6824;070813;232050		
0008	TRK	0587		- 33.4884333333333	- 70.6113733333333	7:16:37 PM	TRK;0587;- 03329.3060;+07036.6824;070813;232243	8/13/2007	16046
0008	TRK	0588		- 33.4884333333333	- 70.6113733333333	7:16:37 PM	TRK;0588;- 03329.3060;+07036.6824;070813;232503	8/13/2007	16047
1234	EOT			0	0		EOT;1234;000269	8/13/2007 7:16:37 PM	16048
1234	SOT			0	0		SOT;1234	8/13/2007 7:21:52 PM	16049
0008	TRK	0589		- 33.4884333333333	- 70.6113733333333	7:21:53 PM	TRK;0589;- 03329.3060;+07036.6824;070813;232642	8/13/2007	16050
0008	TRK	0590		- 33.4884333333333	- 70.6113733333333	7:21:53 PM	TRK;0590;- 03329.3060;+07036.6824;070813;232848	8/13/2007	16051
1234	EOT			0	0		EOT;1234;000125	8/13/2007 7:21:53 PM	16052
1234	SOT			0	0		SOT;1234	8/13/2007 7:26:36 PM	16053
0008	TRK	0591		- 33.4884333333333	- 70.6113733333333	7:26:36 PM	TRK;0591;- 03329.3060;+07036.6824;070813;233109	8/13/2007	16054
0008	TRK	0592		- 33.4882116666667	- 70.6111216666667	7:26:36 PM	TRK;0592;- 03329.2927;+07036.6673;070813;233248	8/13/2007	16055
0008	TRK	0593		- 33.4882116666667	- 70.6111216666667	7:26:37 PM	TRK;0593;- 03329.2927;+07036.6673;070813;233509	8/13/2007	16056
1234	EOT			0	0		EOT;1234;000173	8/13/2007 7:26:37 PM	16057
1234	SOT			0	0		SOT;1234	8/13/2007 7:31:37 PM	16058
0008	TRK	0594		- 33.4882116666667	- 70.6111216666667	7:31:38 PM	TRK;0594;- 03329.2927;+07036.6673;070813;233647	8/13/2007	16059
0008	TRK	0595		- 33.4882116666667	- 70.6111216666667	7:31:38 PM	TRK;0595;- 03329.2927;+07036.6673;070813;233854	8/13/2007	16060
1234	EOT			0	0		EOT;1234;000125	8/13/2007 7:31:38 PM	16061